

Master Obsolescence List

For Magnecraft™ relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|-----------------|------------|----------|---------------------|-----------|---|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 117SIP-23 | P171005E | Obsolete | NA | NA | Contact Customer Service |
| 117SIP-25 | P171015E | Obsolete | NA | NA | Contact Customer Service |
| 117SIP-26 | P171006E | Obsolete | NA | NA | Contact Customer Service |
| 117SIP-5 | P171001E | Obsolete | NA | NA | Contact Customer Service |
| 117SIP-8 | P171003E | Obsolete | 117SIP-3 | P171010E | Replacement product does not have a clamping diode |
| 16-711C1 | I117011 | Obsolete | 16-1351 | P981704E | Clip for 785 relay & socket |
| 16-711C4 | I117012 | Obsolete | 16-1351 | P981704E | Clip for 785 relay & socket |
| 171DIP-15 | P711006E | Obsolete | W171DIP-20 | P711007E | Replacement product has a clamping diode |
| 171DIP-19 | P711025E | Obsolete | 171DIP-14 | P711009E | Replacement product does not have a clamping diode |
| 171DIP-9 | P711005E | Obsolete | W171DIP-4 | P711002E | Replacement product does not have a clamping diode |
| 172DIP-146 | P721022E | Obsolete | W172DIP-150 | P721009E | With clamping diode |
| 172DIP-17 | P727001E | Obsolete | 172DIP-21 | P722002E | Replacement product has a clamping diode |
| 172DIP-24 | P722004E | Obsolete | NA | NA | Contact Customer Service |
| 172DIP-34 | P722005E | Obsolete | NA | NA | Contact Customer Service |
| 172DIP-35 | P722006E | Obsolete | 172DIP-31 | P721006E | Replacement product does not have a clamping diode |
| 172DIP-37 | P721024E | Obsolete | 172DIP-33 | P721007E | Replacement product does not have a clamping diode |
| 172DIP-38 | P722007E | Obsolete | NA | NA | Contact Customer Service |
| 211ACPSOX-18 | F117078 | Obsolete | TDRSOXP-120V | PTDR7020E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211ACPSOX-3 | P117286E | Obsolete | TDRSOXP-24V | PTDR7021E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211ACPSOX-5 | P117079E | Obsolete | TDRSOXP-120V | PTDR7020E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211ACPSOX-6/177 | P117211E | Obsolete | TDRSOXP-120V | PTDR7020E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211ACPSOX-60 | P117110E | Obsolete | TDRSOXP-120V | PTDR7020E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211ACPSOX-61 | F117080 | Obsolete | TDRSOXP-120V | PTDR7020E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211ACPSOX-62 | P117081E | Obsolete | TDRSOXP-120V | PTDR7020E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211ACPSOX-7 | P117083E | Obsolete | TDRSOXP-120V | PTDR7020E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211ACPSOX-8 | P117084E | Obsolete | TDRSOXP-120V | PTDR7020E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211ACPSRX-43A | F117117 | Obsolete | TDRSRXP-120V | PTDR7016E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211ACPSRX-5 | P117085E | Obsolete | TDRSRXP-120V | PTDR7016E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211ACPSRX-60 | P117135E | Obsolete | TDRSRXP-120V | PTDR7016E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|-----------------|------------|----------|---------------------|-----------|---|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 211ACPSRX-7 | P117106E | Obsolete | TDRSRXP-120V | PTDR7016E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211ACPSRX-8 | P117105E | Obsolete | TDRSRXP-120V | PTDR7016E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211CPSOX-1 | P117086E | Obsolete | TDRSOXP-24V | PTDR7021E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211CPSOX-3 | P117097E | Obsolete | TDRSOXP-24V | PTDR7021E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211CPSRX-1 | P117121E | Obsolete | TDRSRXP-24V | PTDR7017E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211CPSRX-3 | P117087E | Obsolete | TDRSRXP-24V | PTDR7017E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 211PROGX-1 | F117109 | Obsolete | TDRPRO-5100 | PTDR7034E | Replacement product has 2 functions instead of 1 & wider timing range; Internal rectifier accepts AC or DC coil voltages resulting in reduction of part numbers |
| 226R-7-12A1 | I261004E | Obsolete | 70S2-04-B-12-N | PS714146E | Not a direct replacement: Larger in size, wider input voltage, 0.187" QC terminals not round push on |
| 226R-8-5A1 | I261001E | Obsolete | 70S2-04-C-12-N | PS714148E | Not a direct replacement: Larger in size, wider input voltage, 0.187" QC terminals not round push on |
| 226RE-7-12A1 | I261009E | Obsolete | 70S2-04-C-10-M | PS714156E | Not a direct replacement: Different pin spacing, wider input voltage, higher ratings |
| 226RE-8-12A1 | I261010E | Obsolete | 70S2-04-C-10-M | PS714156E | Not a direct replacement: Different pin spacing, wider input voltage, higher ratings |
| 250ACPX-40 | D503024 | Obsolete | 750XCXC-120A | P503174E | Not a direct replacement - contact Customer Service |
| 250ACPX-66 | D504035 | Obsolete | 750XAXC-120A | P507258E | Not a direct replacement - contact Customer Service |
| 250AX-33 | D502007 | Obsolete | NA | NA | Contact Customer Service |
| 250CPX-193 | D507071 | Obsolete | 750XBXC-24D | P507203E | Not a direct replacement - contact Customer Service |
| 283CXX102-24D | D833228 | Obsolete | NA | NA | Contact Customer Service |
| 283HXX69C-120A | I831159 | Obsolete | 788HXX69C-120A | P887448E | Direct replacement |
| 283HXX69C-24D | I831136 | Obsolete | 788HXX69C-24D | P887452E | Direct replacement |
| 283XAXC1-120A | I831019 | Obsolete | 788XAXC1-120A | P887478E | Direct replacement |
| 283XAXC1-240A | I831020 | Obsolete | 788XAXC1-240A | P887479E | Direct replacement |
| 283XBX69C-24D | I837179E | Obsolete | 788XBX69C-24D | P887432E | Direct replacement |
| 283XBX69CL-24D | D837248E | Obsolete | 788XBX69CL-24D | P887859E | Direct replacement |
| 283XBXC-24A | I837008E | Obsolete | 788XBXC-24A | P887399E | Direct replacement |
| 283XBXC1-120A | I837019E | Obsolete | 788XBXC1-120A | P887488E | Direct replacement |
| 283XBXC2-120A | D837076E | Obsolete | 788XBXC-120A | P887400E | Not a direct replacement - contact Customer Service |
| 283XBXC2-24A | D837108E | Obsolete | 788XBXC-24A | P887487E | Not a direct replacement - contact Customer Service |
| 283XCX279-24D | I833256 | Obsolete | 788XCXCML-24D | P887179E | Not a direct replacement - contact Customer Service |
| 283XCX287 | I833281 | Obsolete | 788XCXC-24D | P887414E | Not a direct replacement - contact Customer Service |
| 283XCXC-120A | I833008E | Obsolete | 788XCXC-120A | P887410E | Direct replacement |
| 283XCXC1-120A | I833019 | Obsolete | 788XCXC1-120A | P887498E | Direct replacement |
| 283XCXC1-24D | I833013 | Obsolete | 788XCXC1-24D | P887502E | Direct replacement |
| 283XCXC1V2-120A | I833273 | Obsolete | NA | NA | Contact Customer Service |
| 283XCXC2-24D | I833126 | Obsolete | 788XCXC-24D | P887923E | Not a direct replacement - contact Customer Service |
| 283XCXC3-125D | I833269 | Obsolete | 788XCXC3-110D | P887567E | Direct replacement |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|-------------------|------------|----------|---|--------------------------------|--|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 283XCXC3-240A | I833274 | Obsolete | 788XCXC3-240A | P887563E | Direct replacement |
| 283XCXCV-24D | I833272 | Obsolete | 788XCXC-24D + 70-788EL11-1 socket + 70-ASD-250 diode module | P887414E + P707067E + P7M1004E | Not a direct replacement - contact Customer Service |
| 283XXA109 | D831064 | Obsolete | NA | NA | Contact Customer Service |
| 300BXX101 | I002002 | Obsolete | NA | NA | Contact Customer Service |
| 300BXXC1-36D | I002009 | Obsolete | NA | NA | Coil voltage no longer available |
| 300HXX69C1-24D | I001021 | Obsolete | NA | NA | Contact Customer Service |
| 300HXXC1-240A | I001048 | Obsolete | NA | NA | Contact Customer Service |
| 300HXXC1-24D | I001002 | Obsolete | NA | NA | Contact Customer Service |
| 300XBX100 | I007089 | Obsolete | 300XBXC1-240A | C007011 | No difference |
| 300XBX102 | I007094 | Obsolete | NA | NA | Contact Customer Service |
| 300XBX103 | I007097 | Obsolete | NA | NA | Contact Customer Service |
| 300XBX69C1-125D | I007038 | Obsolete | NA | NA | Coil voltage no longer available |
| 300XBX69C1-12D | I007035 | Obsolete | NA | NA | Evaluate 199 Series w/ blow out magnet |
| 300XBX69C1-240A | I007116 | Obsolete | NA | NA | Evaluate 199 Series w/ blow out magnet |
| 300XBX69C4-120A | I007167 | Obsolete | NA | NA | Evaluate 199 Series w/ blow out magnet |
| 300XBX69CT-48D | I007102 | Obsolete | NA | NA | Coil voltage no longer available |
| 300XBXC1-110/125D | I007005 | Obsolete | NA | NA | Coil voltage no longer available |
| 300XBXC1-250D | I007100 | Obsolete | NA | NA | Coil voltage no longer available |
| 300XBXC1-48D | I007079 | Obsolete | NA | NA | Coil voltage no longer available |
| 300XBXC1-6 A | I007090 | Obsolete | NA | NA | Coil voltage no longer available |
| 300XBXC1-6D | I007096 | Obsolete | NA | NA | Coil voltage no longer available |
| 300XBXC1L-120A | I007085 | Obsolete | 300XBXC1-120A | C007010 | No LED on replacement product |
| 300XBXC1LM-120A | I007106 | Obsolete | 300XBXC1-120A | C007010 | No LED or push button on replacement product |
| 300XBXC1LMV2-120A | I007117 | Obsolete | 300XBXC1-120A | C007010 | No LED or push button on replacement product |
| 300XBXC2-110D | I007197 | Obsolete | NA | NA | Coil voltage & anti-rotation tab no longer available |
| 300XBXC2-24D | I007161 | Obsolete | NA | NA | Anti-rotation tab no longer available |
| 300XBXC3-120A | I007127 | Obsolete | 300XBXC1-120A | C007010 | Move to from top flange to side flange |
| 300XBXC3-12D | I007129 | Obsolete | 300XBXC1-12D | C007002 | Move to from top flange to side flange |
| 300XBXC4-120A | I007145 | Obsolete | 300XBXC1-120A | C007010 | Move to from top DIN mount to side flange |
| 300XBXC4-12A | I007166 | Obsolete | 300XBXC1-12A | C007092 | Move to from top DIN mount to side flange |
| 300XBXC4-12D | I007136 | Obsolete | 300XBXC1-12D | C007002 | Move to from top DIN mount to side flange |
| 300XBXC4-240A | I007146 | Obsolete | 300XBXC1-240A | C007011 | Move to from top DIN mount to side flange |
| 300XBXC4-24A | I007152 | Obsolete | 300XBXC1-24A | C007008 | Move to from top DIN mount to side flange |
| 300XBXC4-24D | I007144 | Obsolete | 300XBXC1-24D | C007003 | Move to from top DIN mount to side flange |
| 300XBXC4-48D | I007181 | Obsolete | NA | NA | Coil voltage no longer available |
| 300XBXCLT-120A | I007119 | Obsolete | NA | NA | PCB terminals no longer available |
| 300XBXCT-120A | I007139 | Obsolete | NA | NA | PCB terminals no longer available |
| 300XBXCT-12D | I007104 | Obsolete | NA | NA | PCB terminals no longer available |
| 300XBXCT-48D | I007099 | Obsolete | NA | NA | PCB terminals no longer available |
| 300HXH-220D | I001035 | Obsolete | NA | NA | Coil voltage no longer available |
| 300HXH100 | I001045 | Obsolete | NA | NA | Contact Customer Service |
| 300HXH69C3-74D | I001056 | Obsolete | NA | NA | Coil voltage no longer available |
| 300HXC1-120A | I001007 | Obsolete | NA | NA | Contact Customer Service |
| 300HXC3-120A | I001015 | Obsolete | NA | NA | Contact Customer Service |
| 300HXC3-24D | I001008 | Obsolete | NA | NA | Contact Customer Service |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|----------------|------------|----------|---------------------|----------|--|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 300XHCT-24D | I001041 | Obsolete | NA | NA | PCB terminals no longer available |
| 300XH69CT-60D | I001011 | Obsolete | NA | NA | Coil voltage & PCB terminals no longer available |
| 303BXXC1-12D | I032004 | Obsolete | 785XBXC-12D | I858004E | 303 has side flange option & 30 A rating; 785 requires socket for panel / DIN mounting & 16 A rating |
| 303XBXC1-120A | I037007 | Obsolete | 785XBXC-120A | I858020E | 303 has side flange option & 30 A rating; 785 requires socket for panel / DIN mounting & 16 A rating |
| 303XBXC1-12D | I037005 | Obsolete | 785XBXC-12D | I858004E | 303 has side flange option & 30 A rating; 785 requires socket for panel / DIN mounting & 16 A rating |
| 303XBXC1-24D | I037003 | Obsolete | 785XBXC-24D | I858003E | 303 has side flange option & 30 A rating; 785 requires socket for panel / DIN mounting & 16 A rating |
| 303XBXC4-24D | I037006 | Obsolete | 785XBXC-24D | I858003E | 303 has top DIN mount option & 30 A rating; 785 requires socket for DIN mounting & 16 A rating |
| 314XB236 | D147124 | Obsolete | 750XBXC-6D | P507191E | Not a direct replacement - contact Customer Service |
| 314XB239 | I147111 | Obsolete | 750XB69C-24D | P507127E | Not a direct replacement - contact Customer Service |
| 314XB248 | D147150 | Obsolete | 750XBXC-120A | P507173E | Not a direct replacement - contact Customer Service |
| 314XB258 | I147163 | Obsolete | 750XBXC-120A | P507173E | Not a direct replacement - contact Customer Service |
| 314XB48P-120A | I147014 | Obsolete | 750XBXC-120A | P507173E | Direct replacement |
| 314XB48P-125D | D147144 | Obsolete | 750XBXC-110D | P507215E | Direct replacement |
| 314XB48P-24A | I147013 | Obsolete | 750XBXC-24A | P507161E | Direct replacement |
| 314XB48P-24D | I147018 | Obsolete | 750XBXC-24D | P507203E | Direct replacement |
| 314XB48PGY | D147108 | Obsolete | 750XBXC-48D | P507209E | Not a direct replacement - contact Customer Service |
| 314XC48P-120A | I143014 | Obsolete | 750XCXC-120A | P503174E | Direct replacement |
| 314XC48P-24D | D143018 | Obsolete | 750XCXC-24D | P503204E | Direct replacement |
| 314XC48PLM-28D | D143174 | Obsolete | 750CXM4L-24D | P503014E | Not a direct replacement - contact Customer Service |
| 385XB-120A | P857004EB | Obsolete | 785XBXC-120A | I858020E | 385 has top panel / DIN mount option; 785 requires socket for panel / DIN mounting |
| 385XB-12A | P857009EB | Obsolete | 785XBXC-12A | I858022E | 385 has top panel / DIN mount option; 785 requires socket for panel / DIN mounting |
| 385XB-12D | P857006EB | Obsolete | 785XBXC-12D | I858037E | 385 has top panel / DIN mount option; 785 requires socket for panel / DIN mounting |
| 385XB-24A | P857003EB | Obsolete | 785XBXC-24A | I858021E | 385 has top panel / DIN mount option; 785 requires socket for panel / DIN mounting |
| 385XB-24D | P857001EB | Obsolete | 785XBXC-24D | I858036E | 385 has top panel / DIN mount option; 785 requires socket for panel / DIN mounting |
| 385XDX-120A | P854004EB | Obsolete | (2) 785XBXC-120A | I858020E | 385 has top panel / DIN mount option; 785 requires socket for panel / DIN mounting; two (2) 785 relays & sockets required. |
| 385XDX-12A | P854010EB | Obsolete | (2) 785XBXC-12A | I858022E | 385 has top panel / DIN mount option; 785 requires socket for panel / DIN mounting; two (2) 785 relays & sockets required. |
| 385XDX-12D | P854006EB | Obsolete | (2) 785XBXC-12D | I858037E | 385 has top panel / DIN mount option; 785 requires socket for panel / DIN mounting; two (2) 785 relays & sockets required. |
| 385XDX-24A | P854003EB | Obsolete | (2) 785XBXC-24A | I858021E | 385 has top panel / DIN mount option; 785 requires socket for panel / DIN mounting; two (2) 785 relays & sockets required. |
| 385XDX-24D | P854001EB | Obsolete | (2) 785XBXC-24D | I858036E | 385 has top panel / DIN mount option; 785 requires socket for panel / DIN mounting; two (2) 785 relays & sockets required. |
| 385XF-120A | P856005EB | Obsolete | (3) 785XBXC-120A | I858020E | 385 has top panel / DIN mount option; 785 requires socket for panel / DIN mounting; three (3) 785 relays & sockets required. |
| 385XF-12D | P856001EB | Obsolete | (3) 785XBXC-12D | I858037E | 385 has top panel / DIN mount option; 785 requires socket for panel / DIN mounting; three (3) 785 relays & sockets required. |
| 385XF-24A | P856004E | Obsolete | (3) 785XBXC-24A | I858021E | 385 has top panel / DIN mount option; 785 requires socket for panel / DIN mounting; three (3) 785 relays & sockets required. |
| 385XF-24D | P856002EB | Obsolete | (3) 785XBXC-24D | I858036E | 385 has top panel / DIN mount option; 785 requires socket for panel / DIN mounting; three (3) 785 relays & sockets required. |
| 388CPCX-11 | I883046 | Obsolete | 788XCCTM4L-24D | P887158E | Direct replacement |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|---------------------|------------|----------|---------------------|----------|---|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 388CQX-274 | F883123 | Obsolete | 788XCXC1-12D | P887501E | Direct replacement |
| 388JXBXC-110/125D | I887439 | Obsolete | NA | NA | Contact Customer Service |
| 388JXBXC-120A | I887418E | Obsolete | 389FXBXC-120A | C897077 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket |
| 388JXBXC-12A | I887433B | Obsolete | NA | NA | Contact Customer Service |
| 388JXBXC-12D | I887434 | Obsolete | 389FXBXC-12D | C897086 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket |
| 388JXBXC-220/240A | I887435 | Obsolete | 389FXBXC-240A | C897078 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket |
| 388JXBXC-24A | I887446 | Obsolete | 389FXBXC-24A | C897076 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket |
| 388JXBXC-24D | I887436 | Obsolete | 389FXBXC-24D | C897075 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket |
| 388JXBXC1M-120A | I887330B | Obsolete | 389FXBXC1-120A | C897186 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXBXC1M-12D | I887324EB | Obsolete | 389FXBXC1-12D | C897189 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket |
| 388JXBXC1M-240A | I887331B | Obsolete | 389FXBXC1-240A | C897187 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXBXC1M-24A | I887425B | Obsolete | 389FXBXC1-24A | C897185 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXBXC1M-24D | I887325 | Obsolete | 389FXBXC1-24D | C897190 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket |
| 388JXBXC1M-110/125D | I887463 | Obsolete | NA | NA | Contact Customer Service |
| 388JXBXC1M-120A | I887328B | Obsolete | 389FXBXC1-120A | C897077 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXBXC1M-12D | I887326 | Obsolete | 389FXBXC1-12D | C897086 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXBXC1M-240A | I887329B | Obsolete | 389FXBXC1-240A | C897078 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXBXC1M-24A | I887424B | Obsolete | 389FXBXC1-24A | I897076E | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXBXC1M-24D | I887327B | Obsolete | 389FXBXC1-24D | I897075E | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXCXC-110/125D | I887447 | Obsolete | NA | NA | Contact Customer Service |
| 388JXCXC-120A | I883270B | Obsolete | 389FXCXC-120A | C897213 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket |
| 388JXCXC-12A | I889028B | Obsolete | NA | NA | Contact Customer Service |
| 388JXCXC-12D | I887437 | Obsolete | 389FXCXC-12D | C897162 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket |
| 388JXCXC-220/240A | I887438 | Obsolete | 389FXCXC-240A | C893108 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket |
| 388JXCXC-24A | I889027B | Obsolete | 389FXCXC-24A | C893109 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket |
| 388JXCXC-24D | I883264B | Obsolete | 389FXCXC-24D | C893106 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket |
| 388JXCXC1M-120A | I883243 | Obsolete | 389FXCXC1-120A | C897196 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXCXC1M-12D | I883237B | Obsolete | 389FXCXC1-12D | C897199 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXCXC1M-220/240A | I883244B | Obsolete | 389FXCXC1-240A | C897197 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXCXC1M-24A | I883282B | Obsolete | 389FXCXC1-24A | C897195 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|--------------------|------------|----------|---------------------------------|--------------------|---|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 388JXCXC1M-24D | I883238B | Obsolete | 389FXCXC1-24D | C897200 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXCXCM-110/125D | I883313 | Obsolete | NA | NA | Contact Customer Service |
| 388JXCXCM-120A | I883241B | Obsolete | 389FXCXC-120A | C897213 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXCXCM-12D | I883239 | Obsolete | 389FXCXC-12D | C897162 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXCXCM-220/240A | I883242B | Obsolete | 389FXCXC-240A | C893108 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXCXCM-24A | I883296B | Obsolete | 389FXCXC-24A | C893109 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 388JXCXCM-24D | I883240B | Obsolete | 389FXCXC-24D | C893106 | 389F relay rated 25 A with 0.25" QC terminals. Replacement part compatible with the 70-788EL11-1 socket; no test button |
| 389FHXXC-240A | I897166E | Obsolete | 389FHXXC1-240A | C897204 | Transition from plug-in to side flange mount |
| 389FHXXC1M-240A | I897136E | Obsolete | 389FHXXC1-240A | C897204 | Transition from plug-in to side flange mount. No push button |
| 389FHXXC1M-24D | I897138E | Obsolete | 389FHXXC1-24D | C897206 | No push button |
| 389FXAXC-110D | I897151E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXAXC-120A | I897146E | Obsolete | 389FXAXC1-120A or 389FXCXC-120A | C897176 or C897213 | Available as 1 pole with side flange or 3 pole with clear cover |
| 389FXAXC-12A | I897144E | Obsolete | 389FXCXC1-12A | C897194 | Transition from 1 pole to 3 pole with flange mount |
| 389FXAXC-12D | I897149E | Obsolete | 389FXAXC1-12D | C897179 | Available only with side flange |
| 389FXAXC-220D | I897152E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXAXC-240A | I897147E | Obsolete | 389FXBXC-240A | C897078 | Transition from 1 pole to 2 pole version |
| 389FXAXC-24A | I897145E | Obsolete | 389FXBXC-24A | C897076 | Transition from 1 pole to 2 pole version |
| 389FXAXC-24D | I897150B | Obsolete | 389FXBXC-24D | C897075 | Transition from 1 pole to 2 pole version |
| 389FXAXC-6 A | I897143E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXAXC-6D | I897148E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXAXC1-110D | I897181E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXAXC1-12A | I897174E | Obsolete | 389FXCXC1-12A | C897194 | Transition from 1 pole to 3 pole |
| 389FXAXC1-220D | I897182E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXAXC1-6 A | I897173E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXAXC1-6D | I897178E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXAXC1M-110D | I897121E | Obsolete | NA | NA | Coil voltage & side push button no longer available |
| 389FXAXC1M-120A | I897116E | Obsolete | 389FXAXC1-120A | C897176 | No push button |
| 389FXAXC1M-12A | I897114E | Obsolete | 389FXCXC1-12A | C897194 | Transition from 1 pole to 3 pole (no push button) |
| 389FXAXC1M-12D | I897119E | Obsolete | 389FXAXC1-12D | C897179 | No push button |
| 389FXAXC1M-220D | I897122E | Obsolete | NA | NA | Coil voltage & push button no longer available |
| 389FXAXC1M-240A | I897117E | Obsolete | 389FXAXC1-240A | C897177 | No push button |
| 389FXAXC1M-24A | I897115E | Obsolete | 389FXAXC1-24A | C897175 | No push button |
| 389FXAXC1M-24D | I897120E | Obsolete | 389FXAXC1-24D | C897180 | No push button |
| 389FXAXC1M-6 A | I897113E | Obsolete | NA | NA | Coil voltage & push button no longer available |
| 389FXAXC1M-6D | I897118E | Obsolete | NA | NA | Coil voltage & push button no longer available |
| 389FXBXC-208A | I897073E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXBXC-220D | I897158E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXBXC-6 A | I897153E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXBXC-6D | I897156E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXBXC1-220D | I897192E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXBXC1-6 A | I897183E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXBXC1-6D | I897188E | Obsolete | NA | NA | Coil voltage no longer available |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|------------------|------------|----------|---------------------|---------|--|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 389FXBXC1M-120A | I897054E | Obsolete | 389FXBXC1-120A | C897186 | No push button |
| 389FXBXC1M-12D | I897052E | Obsolete | 389FXBXC1-12D | C897189 | No push button |
| 389FXBXC1M-220D | I897128E | Obsolete | NA | NA | Coil voltage & push button no longer available |
| 389FXBXC1M-240A | I897055E | Obsolete | 389FXBXC1-240A | C897187 | No push button |
| 389FXBXC1M-24A | I897074E | Obsolete | 389FXBXC1-24A | C897185 | No push button |
| 389FXBXC1M-24D | I897053E | Obsolete | 389FXBXC1-24D | C897190 | No push button |
| 389FXBXC1M-6 A | I897123E | Obsolete | NA | NA | Coil voltage & push button no longer available |
| 389FXBXC1M-6D | I897126E | Obsolete | NA | NA | Coil voltage & push button no longer available |
| 389FXBXC3-240A | I897069E | Obsolete | 389FXBXC1-240A | C897187 | Transition from top flange to side flange |
| 389FXBXC3-24A | I897110E | Obsolete | 389FXBXC1-24A | C897185 | Transition from top flange to side flange |
| 389FXBXC4-120A | I897211E | Obsolete | 389FXBXC1-120A | C897186 | Transition from top DIN to side flange |
| 389FXBXC4-24D | I897067E | Obsolete | 389FXBXC1-24D | C897190 | Transition from top DIN to side flange |
| 389FXBXCCL-120A | I897094E | Obsolete | 389FXBXC-120A | C897077 | No LED |
| 389FXBXCCL-12D | I897089E | Obsolete | 389FXBXC-12D | C897086 | No LED |
| 389FXBXCCL-208A | I897095E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXBXCCL-240A | I897096E | Obsolete | 389FXBXC-240A | C897078 | No LED |
| 389FXBXCCL-24A | I897093E | Obsolete | 389FXBXC-24A | C897076 | No LED |
| 389FXBXCCL-24D | I897090E | Obsolete | 389FXBXC-24D | C897075 | No LED |
| 389FXBXCML-120A | I897212E | Obsolete | 389FXBXC-120A | C897077 | No push button or LED |
| 389FXBXCML-24D | I897213E | Obsolete | 389FXBXC-24D | C897075 | No push button or LED |
| 389FXCXC-208A | I893094E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXCXC-220D | I897164E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXCXC-6 A | I897159E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXCXC-6D | I897132E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXCXC1-220D | I897202E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXCXC1-6D | I897198E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXCXC1M-120A | I893076E | Obsolete | 389FXCXC1-120A | C897196 | No push button |
| 389FXCXC1M-12D | I893074E | Obsolete | 389FXCXC1-12D | C897199 | No push button |
| 389FXCXC1M-220D | I897134E | Obsolete | NA | NA | Coil voltage & push button no longer available |
| 389FXCXC1M-240A | I893077E | Obsolete | 389FXCXC1-240A | C897197 | No push button |
| 389FXCXC1M-24A | I893104E | Obsolete | 389FXCXC1-24A | C897195 | No push button |
| 389FXCXC1M-24D | I893075E | Obsolete | 389FXCXC1-24D | C897200 | No push button |
| 389FXCXC1M-6 A | I897129E | Obsolete | NA | NA | Coil voltage & push button no longer available |
| 389FXCXC1M-6D | I897132E | Obsolete | NA | NA | Coil voltage & push button no longer available |
| 389FXCXC3-120A | I893085E | Obsolete | 389FXCXC1-120A | C897196 | Transition from top flange to side flange |
| 389FXCXC3-12D | I893110E | Obsolete | 389FXCXC1-12D | C897199 | Transition from top flange to side flange |
| 389FXCXC3-24A | I893099E | Obsolete | 389FXCXC1-24A | C897195 | Transition from top flange to side flange |
| 389FXCXC3V2-120A | I893090B | Obsolete | 389FXCXC1-120A | C897196 | Transition from top flange to side flange |
| 389FXCXC4-12D | I893111E | Obsolete | 389FXCXC1-12D | C897199 | Transition from top DIN to side flange |
| 389FXCXC4-240A | I893079E | Obsolete | 389FXCXC1-240A | C897197 | Transition from top DIN to side flange |
| 389FXCXC4-24D | I893095E | Obsolete | 389FXCXC1-24D | C897200 | Transition from top DIN to side flange |
| 389FXCXC4M-24D | I893096E | Obsolete | 389FXCXC1-24D | C897200 | Transition from top DIN to side flange. No push button |
| 389FXCXC4V-24D | I893097E | Obsolete | 389FXCXC1-24D | C897200 | Transition from top DIN to side flange |
| 389FXCXCL-120A | I897105E | Obsolete | 389FXCXC-120A | C897213 | No LED |
| 389FXCXCL-12D | I897100E | Obsolete | 389FXCXC-12D | C897162 | No LED |
| 389FXCXCL-208A | I897106E | Obsolete | NA | NA | Coil voltage no longer available |
| 389FXCXCL-240A | I897107E | Obsolete | 389FXCXC-240A | C893108 | No LED |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|---------------------|------------|----------|---------------------|----------|--|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 389FXCXCCL-24A | I897104E | Obsolete | 389FXCXC-24A | C893109 | No LED |
| 389FXCXCCL-24D | I897101E | Obsolete | 389FXCXC-24D | C893106 | No LED |
| 389FXCXCL-120A | I897214E | Obsolete | 389FXCXC-120A | C897213 | No push button or LED |
| 389FXCXCL-24D | I897215E | Obsolete | 389FXCXC-24D | C893106 | No push button or LED |
| 389FXCXCT-12D | I897222E | Obsolete | NA | NA | PCB terminals no longer available |
| 389FXHXC-120A | I897170E | Obsolete | 389FXHXC1-120A | C897208 | Transition from plug-in to side flange model |
| 389FXHXC-12D | I897171E | Obsolete | 389FXHXC1-12D | C897171 | Transition from plug-in to side flange model |
| 389FXHXC-24A | I897169E | Obsolete | 389FXHXC1-24A | C897207 | Transition from plug-in to side flange model |
| 389FXHXC-24D | I897172E | Obsolete | 389FXHXC1-24D | C897210 | Transition from plug-in to side flange model |
| 389FXHXC1M-120A | I897140E | Obsolete | 389FXHXC1-120A | C897208 | Transition from plug-in to side flange model. No push button |
| 389FXHXC1M-12D | I897141E | Obsolete | 389FXHXC1-12D | C897171 | Transition from plug-in to side flange model. No push button |
| 389FXHXC1M-24A | I897139E | Obsolete | 389FXHXC1-24A | C897207 | Transition from plug-in to side flange model. No push button |
| 389FXHXC1M-24D | I897142E | Obsolete | 389FXHXC1-24D | C897210 | No push button |
| 49R1C4VG-12DC-STO | P492017E | Obsolete | 976XBXH-12D | P967006E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49R1C4VG-5DC-STO | P492016E | Obsolete | 976XBXH-5D | P967004E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49R1C4VW-24DC-STO | P492019E | Obsolete | 976XBXH-24D | P967007E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C1VF-50083-STO | P491015E | Obsolete | 976XBXH-24D | P967007E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C1VF-6DC-SIL | P491017E | Obsolete | 976XBXH-6D | P967005E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C1VG-12DC-SIL | P492005E | Obsolete | 976XBXH-12D | P967006E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C1VG-12DC-STO | P492004E | Obsolete | 976XBXH-12D | P967006E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C1VG-18DC-STO | P492029E | Obsolete | NA | NA | Contact Customer Service |
| 49RE1C1VG-24DC-STO | P492006E | Obsolete | 976XBXH-24D | P967007E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C1VG-3DC-SIL | P492001E | Obsolete | NA | NA | Contact Customer Service |
| 49RE1C1VG-5DC-SIL | P492003E | Obsolete | 976XBXH-5D | P967004E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C1VG-5DC-STO | P492002E | Obsolete | 976XBXH-5D | P967004E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C1VW-12DC-STO | P492008E | Obsolete | 976XBXH-12D | P967006E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C1VW-24DC-STO | P492009E | Obsolete | 976XBXH24D | P967007E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C1VW-50080-STO | P491013E | Obsolete | 976XAXH-24D | P961008E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C1VW-50082-STO | P491014E | Obsolete | 976XAXH-12D | P961012E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C1VW-50085-STO | P491016E | Obsolete | 976XAXH-12D | P961012E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C1VW-5DC-STO | P492007E | Obsolete | 976XAXH-5D | P961010E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C2VF-12DC-SIL | P492013E | Obsolete | 976XBXH-12D | P967006E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C2VF-6DC-SCO | P492010 | Obsolete | 976XBXH-6D | P967005E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 49RE1C2VF-6DC-SIL | P492011E | Obsolete | 796XBXH-6D | P967005E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|-------------------|------------|----------|---------------------|-----------|--|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 49RE1C2VF-6DC-STO | P492010E | Obsolete | 796XBXH-6D | P967005E | Different PCB footprint & contact configuration (49 relay is SPDT & 976 relay is DPDT) |
| 60HE1S-12DC | P601002E | Obsolete | 276XAXH-12D | I761011E | Not a direct replacement: Check product size & pin spacings |
| 60HE1S-24DC | P601003E | Obsolete | 276XAXH-24D | I761012E | Not a direct replacement: Check product size & pin spacings |
| 60HE1S-48DC | P601004 | Obsolete | NA | NA | Contact Customer Service |
| 60HE1S-5DC | P601006E | Obsolete | 276XAXH-5D | I761008E | Not a direct replacement: Check product size & pin spacings |
| 60HE2S-12DC | P607002E | Obsolete | 976XBXH-12D | P967006E | Not a direct replacement: Check product size & pin spacings |
| 60HE2S-24DC | P607003E | Obsolete | 976XBXH-24D | P967007E | Not a direct replacement: Check product size & pin spacings |
| 60HE2S-48DC | P607004E | Obsolete | NA | NA | Contact Customer Service |
| 70S2-01-A-03-K | PS714230E | Obsolete | 861SSR208-DD | I611014E | Not a direct replacement: Replacement product does not require socket & can be mounted directly onto DIN rail or panel. Check product form & fit |
| 70S2-02-A-03-F | PS714232E | Obsolete | 70S2-01-A-03-V | PS714201E | Not a direct replacement: Different pin spacing, input voltage range |
| 70S2-02-A-03-V | PS714236E | Obsolete | 70S2-01-A-03-V | PS714201E | Not a direct replacement: Check input voltage range |
| 70S2-03-C-15-D | PS714053 | Obsolete | 70S2-04-C-12-N | PS714148E | Not a direct replacement: Check ratings & product size |
| 70S2-04-B-02-H | PS714064E | Obsolete | 70S2-04-B-03-V | PS714182E | Not a direct replacement: Different pin spacing |
| 70S2-04-B-04-K | PS714088E | Obsolete | 861SSR210-DC-1 | I611001E | Not a direct replacement: Replacement product does not require socket & can be mounted directly onto DIN rail or panel. Check product form & fit |
| 70S2-04-B-05-V | PS714387 | Obsolete | 70S2-04-B-03-V | PS714182E | Not a direct replacement: Check ratings |
| 70S2-04-B-06-L | PS714158 | Obsolete | 70S2-04-C-10-M | PS714156E | Not a direct replacement: Different pin spacing |
| 70S2-04-B-06-M | PS714150E | Obsolete | 70S2-04-C-10-M | PS714156E | Replacement product has a wider output voltage range |
| 70S2-04-B-10-M | PS714154E | Obsolete | 70S2-04-C-10-M | PS714156E | Replacement product has a wider output voltage range |
| 70S2-04-C-02-H | PS714081E | Obsolete | 70S2-04-C-03-V | PS714184E | Not a direct replacement: Different pin spacing |
| 70S2-04-C-04-K | PS714090E | Obsolete | 861SSR210-DC-1 | I611001E | Not a direct replacement: Replacement product does not require socket & can be mounted directly onto DIN rail or panel. Check product form & fit |
| 70S2-04-C-05-V | PS714388E | Obsolete | 70S2-04-C-03-V | PS714184E | Not a direct replacement: Check ratings |
| 70S2-04-C-06-L | PS714160E | Obsolete | 70S2-04-C-10-M | PS714156E | Not a direct replacement: Different pin spacing |
| 70S2-04-D-02-H | PS714080E | Obsolete | 70S2-04-D-03-V | PS714186E | Not a direct replacement: Different pin spacing |
| 70S2-04-D-04-F | PS714075E | Obsolete | 70S2-04-D-03-V | PS714186E | Not a direct replacement: Check ratings & pin spacing |
| 70S2-05-B-02-H | PS714098E | Obsolete | 70S2-04-B-03-V | PS714182E | Not a direct replacement: Different pin spacing |
| 70S2-05-B-04-F | PS714058E | Obsolete | 70S2-04-C-03-V | PS714184E | Not a direct replacement: Check ratings & pin spacing |
| 70S2-05-B-06-S | PS714191E | Obsolete | 70S2-05-C-12-S | PS714197E | Replacement product has higher current ratings & wider output voltage range |
| 70S2-05-B-12-S | PS714195E | Obsolete | 70S2-05-C-12-S | PS714197E | Replacement product has higher current ratings & wider output voltage range |
| 70S2-05-C-03-V | PS714185E | Obsolete | 70S2-04-C-03-V | PS714184E | Replacement product has a wider input voltage range |
| 70S2-05-C-04-K | PS714091E | Obsolete | 861SSR210-DC-1 | I611001E | Not a direct replacement: Replacement product does not require socket & can be mounted directly onto DIN rail or panel. Check product form & fit |
| 70S2-05-C-06-N | PS714145 | Obsolete | 70S2-04-C-12-N | PS714148E | Replacement product has higher current ratings |
| 70S2-05-C-06-S | PS714193 | Obsolete | 70S2-05-C-12-S | PS714197E | Replacement product has higher current ratings & wider output voltage range |
| 70S2-05-C-12-N | PS714149E | Obsolete | 70S2-04-C-12-N | PS714148E | Replacement product has a wider input voltage range |
| 70S2-05-D-04-K | PS714211E | Obsolete | 861SSR210-DC-1 | I611001E | Not a direct replacement: Replacement product does not require socket & can be mounted directly onto DIN rail or panel. Check product form & fit |
| 70S2-06-B-12-N | PS714352E | Obsolete | 70S2-04-B-12-N | PS714146E | Direct replacement |
| 70YY14116 | PS714116E | Obsolete | 70S2-04-C-10-M | PS714156E | Not a direct replacement: Different pin spacing & switching frequency 25 to 70hz (not 400hz) |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|---------------------|------------|----------|---------------------|-----------|---|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 70YY14141 | PS714141 | Obsolete | 70S2-04-C-03-V | PS714184E | Not a direct replacement: Review input / output voltage range, ratings & pin spacing |
| 70YY14260-2 | PS714260E | Obsolete | 70S2-04-C-06-N | PS714144E | Replacement product has a wider input voltage range & higher ratings |
| 70YY14264 | PS714264E | Obsolete | 70S2-04-B-03-V | PS714182E | Not a direct replacement: Different switching frequency 25 to 70hz (not 400hz) |
| 70YY14279 | PS714279E | Obsolete | 70S2-03-C-25-S | PS714209E | Replacement product has a 3 - 30 VDC control voltage |
| 70YY14281-2 | PS714281E | Obsolete | 70S2-04-C-12-S | PS714196E | Replacement product has a 24 - 280 VAC output voltage range (not 480 VAC) |
| 70YY14325 | PS714325E | Obsolete | 70S2-01-A-03-V | PS714201E | Not a direct replacement: Load voltage range is 3 - 60 VDC (not 4 - 150 VDC) |
| 70YY14330 | PS714330E | Obsolete | 70S2-03-C-25-S | PS714209E | Replacement product has a wider input voltage range |
| 70YY14342 | PS714342E | Obsolete | 70S2-04-C-12-S | PS714196E | Direct replacement |
| 711XBXCL-110D | I117008E | Obsolete | 785XBXC-110D | I858001E | 711 is an impulse sequencing relay - 785 is a latching relay; refer to the catalog & drawings for proper operation. 711 relay uses LED; 785 requires 70-788EL11-1 socket with LED module. |
| 711XBXCL-120A | I117010E | Obsolete | 785XBXC-120A | I858020E | 711 is an impulse sequencing relay - 785 is a latching relay; refer to the catalog & drawings for proper operation. 711 relay uses LED; 785 requires 70-788EL11-1 socket with LED module. |
| 711XBXCL-12D | I117005E | Obsolete | 785XBXC-12D | I858004E | 711 is an impulse sequencing relay - 785 is a latching relay; refer to the catalog & drawings for proper operation. 711 relay uses LED; no LED module available for this 785 relay |
| 711XBXCL-24A | I117009E | Obsolete | 785XBXC-24A | I858021E | 711 is an impulse sequencing relay - 785 is a latching relay; refer to the catalog & drawings for proper operation. 711 relay uses LED; 785 requires 70-788EL11-1 socket with LED module. |
| 711XBXCL-24D | I117006E | Obsolete | 785XBXC-24D | I858003E | 711 is an impulse sequencing relay - 785 is a latching relay; refer to the catalog & drawings for proper operation. 711 relay uses LED; 785 requires 70-788EL11-1 socket with LED module. |
| 711XBXCL-48D | I117007E | Obsolete | 785XBXC-48D | I858212E | 711 is an impulse sequencing relay - 785 is a latching relay; refer to the catalog & drawings for proper operation. 711 relay uses LED; no LED module available for this 785 relay |
| 712XAXC-120V | P121002E | Obsolete | NA | NA | Contact Customer Service |
| 712XBXC-120V | P121006E | Obsolete | NA | NA | Contact Customer Service |
| 712XBXC-240A | P121007E | Obsolete | NA | NA | Contact Customer Service |
| 712XBXC-24V | P121005E | Obsolete | NA | NA | Contact Customer Service |
| 712XBXCCK-120V | P121010E | Obsolete | NA | NA | Contact Customer Service |
| 712XBXCCK1-120V | P121014E | Obsolete | NA | NA | Contact Customer Service |
| 750XAX1M4L-120A | P507426E | Obsolete | NA | NA | Contact Customer Service |
| 750XAX1M4L-12A | P507424E | Obsolete | NA | NA | Contact Customer Service |
| 750XAX1M4L-12D | P507428E | Obsolete | NA | NA | Contact Customer Service |
| 750XAX1M4L-220/240A | P507427E | Obsolete | NA | NA | Contact Customer Service |
| 750XAX1M4L-24A | P507425E | Obsolete | NA | NA | Contact Customer Service |
| 750XAX1M4L-24D | P507429E | Obsolete | NA | NA | Contact Customer Service |
| 750XAX1M4L-48D | P507464E | Obsolete | NA | NA | Contact Customer Service |
| 750XAX1M4L-6 A | P507462E | Obsolete | NA | NA | Contact Customer Service |
| 750XAX1M4L-6D | P507463E | Obsolete | NA | NA | Contact Customer Service |
| 750XAXC-120A | P507258E | Obsolete | 750XBXRC-120A | C507173 | Replacement product is rated 10 A & has 2 poles |
| 750XAXC-12A | P507449E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XAXC-12D | P507259E | Obsolete | 750XBXRC-12D | C507197 | Replacement product is rated 10 A & has 2 poles |
| 750XAXC-220/240A | P507450E | Obsolete | 750XBXRC-240A | C507185 | Replacement product is rated 10 A & has a 240 VAC coil |
| 750XAXC-24A | P507257E | Obsolete | 750XBXRC-24A | C507161 | Replacement product is rated 10 A & has 2 poles |
| 750XAXC-24D | P507260E | Obsolete | 750XBXRC-24D | C507203 | Replacement product is rated 10 A & has 2 poles |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|--------------------|------------|----------|---------------------|---------|--|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 750XAXC-48D | P507452E | Obsolete | 750XBXRC-48D | C507209 | Replacement product is rated 10 A & has 2 poles |
| 750XAXC-6 A | P507448E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XAXC-6D | P507451E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XAXCL-110D | P507266E | Obsolete | NA | NA | Contact Customer Service |
| 750XAXCL-12A | P507496E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XAXCL-12D | P507264E | Obsolete | 750XBXRCL-12D | C507198 | Replacement product is rated 10 A & has 2 poles |
| 750XAXCL-240A | P507478E | Obsolete | 750XBXRCL-240A | C507186 | Replacement product is rated 10 A & has 2 poles |
| 750XAXCL-24A | P507262E | Obsolete | 750XBXRCL-24A | C507162 | Replacement product is rated 10 A & has 2 poles |
| 750XAXCL-24D | P507265E | Obsolete | 750XBXRCL-24D | C507204 | Replacement product is rated 10 A & has 2 poles |
| 750XAXCL-6 A | P507501E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XAXCL-6D | P507502E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XAXM4L-120A | P507456E | Obsolete | 750XBXR4L-120A | C507010 | Replacement product is rated 10 A & has 2 poles |
| 750XAXM4L-12A | P507454E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XAXM4L-12D | P507479E | Obsolete | 750XBXR4L-12D | C507013 | Replacement product is rated 10 A & has 2 poles |
| 750XAXM4L-220/240A | P507457E | Obsolete | NA | NA | Contact Customer Service |
| 750XAXM4L-24A | P507455E | Obsolete | 750XBXR4L-24A | C507009 | Replacement product is rated 10 A & has 2 poles |
| 750XAXM4L-24D | P507459E | Obsolete | 750XBXR4L-24D | C507014 | Replacement product is rated 10 A & has 2 poles |
| 750XAXM4L-48D | P507460E | Obsolete | 750XBXR4L-48D | C507008 | Replacement product is rated 10 A & has 2 poles |
| 750XAXM4L-6 A | P507453E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XAXM4L-6D | P507458E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XB69C-110D | P507128E | Obsolete | 750XBXRC-110D | C507215 | Replacement product is rated 10 A |
| 750XB69C-12A | P507491E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XB69C-12D | P507126E | Obsolete | 750XBXRC-12D | C507197 | Replacement product is rated 10 A |
| 750XB69C-240A | P507255E | Obsolete | 750XBXRC-240A | C507185 | Replacement product is rated 10 A |
| 750XB69C-24A | P507124E | Obsolete | 750XBXRC-24A | C507161 | Replacement product is rated 10 A |
| 750XB69C-24D | P507127E | Obsolete | 750XBXRC-24D | C507203 | Replacement product is rated 10 A |
| 750XB69C-6 A | P507493E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XB69C-6D | P507494E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XBXC-110/125D | P507215E | Obsolete | 750XBXRC-110D | C507215 | Replacement product is rated 10 A |
| 750XBXC-120A | P507173E | Obsolete | 750XBXRC-120A | C507173 | Replacement product is rated 10 A |
| 750XBXC-12A | P507155E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XBXC-12D | P507197E | Obsolete | 750XBXRC-12D | C507197 | Replacement product is rated 10 A |
| 750XBXC-220/240A | P507185E | Obsolete | 750XBXRC-240A | C507185 | Replacement product is rated 10 A & has a 240 VAC coil |
| 750XBXC-24A | P507161E | Obsolete | 750XBXRC-24A | C507161 | Replacement product is rated 10 A |
| 750XBXC-24D | P507203E | Obsolete | 750XBXRC-24D | C507203 | Replacement product is rated 10 A |
| 750XBXC-48D | P507209E | Obsolete | 750XBXRC-48D | C507209 | Replacement product is rated 10 A |
| 750XBXC-6 A | P507149E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XBXC-6D | P507191E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XBXCL-110D | P507216E | Obsolete | 750XBXRCL-110D | C507216 | Replacement product is rated 10 A |
| 750XBXCL-12A | P507156E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XBXCL-12D | P507198E | Obsolete | 750XBXRCL-12D | C507198 | Replacement product is rated 10 A |
| 750XBXCL-24A | P507162E | Obsolete | 750XBXRCL-24A | C507162 | Replacement product is rated 10 A |
| 750XBXCL-24D | P507204E | Obsolete | 750XBXRCL-24D | C507204 | Replacement product is rated 10 A |
| 750XBXCL-6 A | P507150E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XBXCL-6D | P507192E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XBXH-220D | P507085E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XBXH-48A | P507089E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|--------------------|------------|----------|---------------------|---------|--|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 750BXH-48D | P507083E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750BXH-6 A | P507086E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750BXH-6D | P507080E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750BXM4L-110/125D | P507015E | Obsolete | 750XBXM4L-110D | C507015 | Replacement product is rated 10 A |
| 750BXM4L-120A | P507010E | Obsolete | 750XBXM4L-120A | C507010 | Replacement product is rated 10 A |
| 750BXM4L-12A | P507006E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750BXM4L-12D | P507013E | Obsolete | 750XBXM4L-12D | C507013 | Replacement product is rated 10 A |
| 750BXM4L-220/240A | P507011E | Obsolete | 750XBXM4L-240A | C507011 | Replacement product is rated 10 A & has a 240 VAC coil |
| 750BXM4L-24A | P507009E | Obsolete | 750XBXM4L-24A | C507009 | Replacement product is rated 10 A |
| 750BXM4L-24D | P507014E | Obsolete | 750XBXM4L-24D | C507014 | Replacement product is rated 10 A |
| 750BXM4L-48D | P507008E | Obsolete | 750XBXM4L-48D | C507008 | Replacement product is rated 10 A |
| 750BXM4L-6 A | P507004E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750BXM4L-6D | P507017E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XCXC-110/125D | P503216E | Obsolete | 750XCXRC-110D | C507217 | Replacement product is rated 10 A |
| 750XCXC-120A | P503174E | Obsolete | 750XCXRC-120A | C503174 | Replacement product is rated 10 A |
| 750XCXC-12A | P503156E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XCXC-12D | P503198E | Obsolete | 750XCXRC-12D | C503198 | Replacement product is rated 10 A |
| 750XCXC-220/240A | P503186E | Obsolete | 750XCXRC-240A | C503186 | Replacement product is rated 10 A & has a 240 VAC coil |
| 750XCXC-24A | P503162E | Obsolete | 750XCXRC-24A | C503162 | Replacement product is rated 10 A |
| 750XCXC-24D | P503204E | Obsolete | 750XCXRC-24D | C503204 | Replacement product is rated 10 A |
| 750XCXC-48D | P503210E | Obsolete | 750XCXRC-48D | C503210 | Replacement product is rated 10 A |
| 750XCXC-6 A | P503150E | Obsolete | NA | NA | Replacement product is rated 10 A |
| 750XCXC-6D | P503192E | Obsolete | NA | NA | Replacement product is rated 10 A |
| 750XCXCL-110D | P503217E | Obsolete | 750XCXRCL-110D | C503217 | Replacement product is rated 10 A |
| 750XCXCL-12A | P503157E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XCXCL-12D | P503199E | Obsolete | 750XCXRCL-12D | C503199 | Replacement product is rated 10 A |
| 750XCXCL-24A | P503163E | Obsolete | 750XCXRCL-24A | C503163 | Replacement product is rated 10 A |
| 750XCXCL-24D | P503205E | Obsolete | 750XCXRCL-24D | C503205 | Replacement product is rated 10 A |
| 750XCXCL-6 A | P503151E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XCXCL-6D | P503193E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XCXH-220D | P503087E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XCXH-48A | P503091E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XCXH-48D | P503085E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XCXH-6 A | P503088E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XCXH-6D | P503082E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XCXM4L-110/125D | P503015E | Obsolete | 750XCXRM4L-110 | C503015 | Replacement product is rated 10 A |
| 750XCXM4L-120A | P503010E | Obsolete | 750XCXRM4L-120A | C503010 | Replacement product is rated 10 A |
| 750XCXM4L-12A | P503006E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XCXM4L-12D | P503013E | Obsolete | 750XCXRM4L-12D | C503013 | Replacement product is rated 10 A |
| 750XCXM4L-220/240A | P503011E | Obsolete | 750XCXRM4L-240A | C503011 | Transition to to 240 A coil Voltage |
| 750XCXM4L-24A | P503009E | Obsolete | 750XCXRM4L-24A | C503009 | Replacement product is rated 10 A |
| 750XCXM4L-24D | P503014E | Obsolete | 750XCXRM4L-24D | C503014 | Replacement product is rated 10 A |
| 750XCXM4L-48D | P503008E | Obsolete | 750XCXRM4L-48D | C503008 | Replacement product is rated 10 A |
| 750XCXM4L-6 A | P503004E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 750XCXM4L-6D | P503007E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 755BXC-120A | P557004E | Obsolete | NA | NA | Contact Customer Service |
| 755BXC-240A | P557005E | Obsolete | NA | NA | Contact Customer Service |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|-------------------|------------|----------|---------------------|---------|--|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 755XBXC-24A | P557003E | Obsolete | NA | NA | Contact Customer Service |
| 755XBXCD-110D | P557010E | Obsolete | NA | NA | Contact Customer Service |
| 755XBXCD-12D | P557007E | Obsolete | NA | NA | Contact Customer Service |
| 755XBXCD-24D | P557008E | Obsolete | NA | NA | Contact Customer Service |
| 781XAX3C-110D | P811250EB | Obsolete | 792XDX3C-110D | C924171 | Replacement product is 4-pole relay with identical ratings. New socket required. |
| 781XAX3C-120A | P811303EB | Obsolete | 792XDX3C-120A | C924123 | Replacement product is 4-pole relay with identical ratings. New socket required. |
| 781XAX3C-12A | P811304EB | Obsolete | 792XDX3C-12A | C924156 | Replacement product is 4-pole relay with identical ratings. New socket required. |
| 781XAX3C-12D | P811304EB | Obsolete | 792XDX3C-12D | C924125 | Replacement product is 4-pole relay with identical ratings. New socket required. |
| 781XAX3C-220/230A | P811305EB | Obsolete | 792XDX3C-240A | C924155 | Replacement product is 4-pole relay with identical ratings; transition to standard 240 VAC coil. New socket required |
| 781XAX3C-240A | P811305EB | Obsolete | 792XDX3C-240A | C924155 | Replacement product is 4-pole relay with identical ratings. New socket required. |
| 781XAX3C-24A | P811306EB | Obsolete | 792XDX3C-24A | C924124 | Replacement product is 4-pole relay with identical ratings. New socket required. |
| 781XAX3C-24D | P811307EB | Obsolete | 792XDX3C-24D | C924126 | Replacement product is 4-pole relay with identical ratings. New socket required. |
| 781XAX3M4L-110D | P811250EB | Obsolete | 792XDX3M4L-110D | C924014 | Replacement product is 4-pole relay with identical ratings. New socket required. |
| 781XAX3M4L-120A | P811244EB | Obsolete | 792XDX3M4L-120A | C924009 | Replacement product is 4-pole relay with identical ratings. New socket required. |
| 781XAX3M4L-12D | P811248EB | Obsolete | 792XDX3M4L-12D | C924012 | Replacement product is 4-pole relay with identical ratings. New socket required. |
| 781XAX3M4L-240A | P811247EB | Obsolete | 792XDX3M4L-240A | C924011 | Replacement product is 4-pole relay with identical ratings. New socket required. |
| 781XAX3M4L-24A | P811245EB | Obsolete | 792XDX3M4L-24A | C924008 | Replacement product is 4-pole relay with identical ratings. New socket required. |
| 781XAX3M4L-24D | P811249EB | Obsolete | 792XDX3M4L-24D | C924013 | Replacement product is 4-pole relay with identical ratings. New socket required. |
| 781XAXC-110D | P811086EB | Obsolete | 781XAXRC-110D | C811086 | Replacement product is rated 15 A |
| 781XAXC-120A | P811082EB | Obsolete | 781XAXRC-120A | C811082 | Replacement product is rated 15 A |
| 781XAXC-12A | P811084EB | Obsolete | 781XAXRC-12A | C811084 | Replacement product is rated 15 A |
| 781XAXC-12D | P811088EB | Obsolete | 781XAXRC-12D | C811088 | Replacement product is rated 15 A |
| 781XAXC-220/230A | P811121EB | Obsolete | 781XAXRC-240A | C811081 | Replacement product is rated 15 A; transition to standard 240 VAC coil version |
| 781XAXC-240A | P811081EB | Obsolete | 781XAXRC-240A | C811081 | Replacement product is rated 15 A |
| 781XAXC-24A | P811083EB | Obsolete | 781XAXRC-24A | C811083 | Replacement product is rated 15 A |
| 781XAXC-24D | P811087EB | Obsolete | 781XAXRC-24D | C811087 | Replacement product is rated 15 A |
| 781XAXC-48A | P811300EB | Obsolete | 781XAXRC-48A | C811300 | Replacement product is rated 15 A |
| 781XAXC-48D | P811135EB | Obsolete | 781XAXRC-48D | C811135 | Replacement product is rated 15 A |
| 781XAXC-6 A | P811085EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 781XAXC-6D | P811089EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 781XAXCL-110D | P811061EB | Obsolete | 781XAXRCL-110D | C811061 | Replacement product is rated 15 A |
| 781XAXCL-120A | P811057EB | Obsolete | 781XAXRCL-120A | C811057 | Replacement product is rated 15 A |
| 781XAXCL-12A | P811059EB | Obsolete | 781XAXRCL-12A | C811059 | Replacement product is rated 15 A |
| 781XAXCL-12D | P811063EB | Obsolete | 781XAXRCL-12D | C811063 | Replacement product is rated 15 A |
| 781XAXCL-220/230A | P811122EB | Obsolete | 781XAXRCL-240A | C811056 | Replacement product is rated 15 A; transition to standard 240 VAC coil version |
| 781XAXCL-240A | P811056EB | Obsolete | 781XAXRCL-240A | C811056 | Replacement product is rated 15 A |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|--------------------|------------|----------|---------------------|---------|---|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 781XAXCL-24A | P811058EB | Obsolete | 781XAXRCL-24A | C811058 | Replacement product is rated 15 A |
| 781XAXCL-24D | P811062EB | Obsolete | 781XAXRCL-24D | C811062 | Replacement product is rated 15 A |
| 781XAXCL-48A | P811309EB | Obsolete | 781XAXRCL-48A | C811309 | Replacement product is rated 15 A |
| 781XAXCL-48D | P811136EB | Obsolete | 781XAXRCL-48D | C811136 | Replacement product is rated 15 A |
| 781XAXCL-6 A | P811060EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 781XAXCL-6D | P811064EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 781XAXM4L-110/125D | P811226EB | Obsolete | 781XAXRM4L-110D | C811226 | Replacement product is rated 15 A; transition to standard 110 VDC coil version |
| 781XAXM4L-120A | P811232EB | Obsolete | 781XAXRM4L-120A | C811232 | Replacement product is rated 15 A |
| 781XAXM4L-12A | P811234EB | Obsolete | 781XAXRM4L-12A | C811234 | Replacement product is rated 15 A |
| 781XAXM4L-12D | P811229EB | Obsolete | 781XAXRM4L-12D | C811229 | Replacement product is rated 15 A |
| 781XAXM4L-220/230A | P811243EB | Obsolete | 781XAXRM4L-240A | C811231 | Replacement product is rated 15 A; transition to standard 240 VAC coil version |
| 781XAXM4L-240A | P811231EB | Obsolete | 781XAXRM4L-240A | C811231 | Replacement product is rated 15 A |
| 781XAXM4L-24A | P811233EB | Obsolete | 781XAXRM4L-24A | C811233 | Replacement product is rated 15 A |
| 781XAXM4L-24D | P811228EB | Obsolete | 781XAXRM4L-24D | C811228 | Replacement product is rated 15 A |
| 781XAXM4L-48A | P811308EB | Obsolete | 781XAXRM4L-48A | C811308 | Replacement product is rated 15 A |
| 781XAXM4L-48D | P811227EB | Obsolete | 781XAXRM4L-48D | C811227 | Replacement product is rated 15 A |
| 781XAXM4L-6 A | P811235EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 781XAXM4L-6D | P811230EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 782XAXC-110/125D | P821008EB | Obsolete | NA | NA | Contact Customer Service |
| 782XAXC-110D | P821008EB | Obsolete | 782XBXC-110D | C827138 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXC-120A | P821003EB | Obsolete | 782XBXC-120A | C827144 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXC-12A | P821001EB | Obsolete | 782XBXC-12A | C824389 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXC-12D | P821006EB | Obsolete | 782XBXC-12D | C827141 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXC-220/230A | P824486EB | Obsolete | 782XBXC-240A | C827143 | Replacement product is 2-pole relay with 15 A ratings; transition to standard 240 VAC coil. New socket required |
| 782XAXC-220/240A | P821004EB | Obsolete | NA | NA | Contact Customer Service |
| 782XAXC-240A | P821004EB | Obsolete | 782XBXC-240A | C827143 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXC-24A | P821002EB | Obsolete | 782XBXC-24A | C827145 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXC-24D | P821007EB | Obsolete | 782XBXC-24D | C827140 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXC-48A | P827829EB | Obsolete | 782XBXC-48A | C827824 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXC-48D | P821078EB | Obsolete | 782XBXC-48D | C827139 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXC-6 A | P821039EB | Obsolete | 782XBXC-6 A | NA | Contact Customer Service |
| 782XAXC-6D | P821005EB | Obsolete | 782XBXC-6D | NA | Contact Customer Service |
| 782XAXCL-110D | P821084EB | Obsolete | 782XBXC-110D | C824391 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXCL-120A | P821010EB | Obsolete | 782XBXC-120A | C827571 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXCL-12A | P821047EB | Obsolete | 782XBXC-12A | C824392 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXCL-12D | P821069EB | Obsolete | 782XBXC-12D | C824393 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|--------------------|------------|----------|---------------------|---------|---|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 782XAXCL-220/230A | P824487EB | Obsolete | 782XBXC-240A | C824394 | Replacement product is 2-pole relay with 15 A ratings; transition to standard 240 VAC coil. New socket required |
| 782XAXCL-240A | P821011EB | Obsolete | 782XBXC-240A | C824394 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXCL-24A | P821009EB | Obsolete | 782XBXC-24A | C827570 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXCL-24D | P821012EB | Obsolete | 782XBXC-24D | C824395 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXCL-48A | P827828EB | Obsolete | 782XBXC-48A | C827823 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXCL-48D | P821079EB | Obsolete | 782XBXC-48D | C827822 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXCL-6 A | P821040EB | Obsolete | 782XBXC-6 A | NA | Contact Customer Service to transition to different coil voltage |
| 782XAXCL-6D | P821064EB | Obsolete | 782XBXC-6D | NA | Contact Customer Service to transition to different coil voltage |
| 782XAXM4L-110/125D | P821024EB | Obsolete | NA | NA | Contact Customer Service |
| 782XAXM4L-110D | P821024EB | Obsolete | 782XBXM4L-110D | C827009 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXM4L-120A | P821026EB | Obsolete | 782XBXM4L-120A | C827002 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXM4L-12A | P821045E | Obsolete | 782XBXM4L-12A | C827102 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXM4L-12D | P821021EB | Obsolete | 782XBXM4L-12D | C827006 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXM4L-220/230A | P821027EB | Obsolete | 782XBXM4L-240A | C827004 | Replacement product is 2-pole relay with 15 A ratings; transition to standard 240 VAC coil. New socket required |
| 782XAXM4L-220/240A | P821028EB | Obsolete | NA | NA | Contact Customer Service |
| 782XAXM4L-240A | P821028EB | Obsolete | 782XBXM4L-240A | C827004 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXM4L-24A | P821025EB | Obsolete | 782XBXM4L-24A | C827001 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXM4L-24D | P821022EB | Obsolete | 782XBXM4L-24D | C827007 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXM4L-48A | P827830EB | Obsolete | 782XBXM4L-48A | C827826 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXM4L-48D | P821023EB | Obsolete | 782XBXM4L-48D | C827008 | Replacement product is 2-pole relay with 15 A ratings. New socket required. |
| 782XAXM4L-6 A | P821038EB | Obsolete | 782XBXM4L-6 A | NA | Contact Customer Service to transition to different coil voltage |
| 782XAXM4L-6D | P821020EB | Obsolete | 782XBXM4L-6D | NA | Contact Customer Service to transition to different coil voltage |
| 782XBXC-110/125D | P827587EB | Obsolete | NA | NA | Contact Customer Service |
| 782XBXC-120A | P827590EB | Obsolete | 792XBXC-120A | C927590 | Exact replacement. 792XB relays have higher rating of 12A |
| 782XBXC-12A | P827588EB | Obsolete | 792XBXC-12A | C927588 | Exact replacement. 792XB relays have higher rating of 12A |
| 782XBXC-12D | P827689EB | Obsolete | 792XBXC-12D | C927689 | Exact replacement. 792XB relays have higher rating of 12A |
| 782XBXC-220/240A | P827591EB | Obsolete | 792XBXC-240A | C927591 | Exact replacement. 792XB relays have higher rating of 12A |
| 782XBXC-24A | P827589EB | Obsolete | 792XBXC-24A | C927589 | Exact replacement. 792XB relays have higher rating of 12A |
| 782XBXC-24D | P827586EB | Obsolete | 792XBXC-24D | C927586 | Exact replacement. 792XB relays have higher rating of 12A |
| 782XBXC-48D | P827818EB | Obsolete | 792XBXC-48D | C927818 | Exact replacement. 792XB relays have higher rating of 12A |
| 782XBXC-6 A | P827816EB | Obsolete | NA | NA | Contact Customer Service |
| 782XBXC-6D | P827584EB | Obsolete | NA | NA | Contact Customer Service |
| 782XBXC-12A | P827873EB | Obsolete | NA | NA | Contact Customer Service |
| 782XBXC-12D | P827874EB | Obsolete | NA | NA | Contact Customer Service |
| 782XBXC-240A | P827875EB | Obsolete | NA | NA | Contact Customer Service |
| 782XBXC-24A | P827876EB | Obsolete | NA | NA | Contact Customer Service |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|--------------------|------------|----------|---------------------|---------|--|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 782XB2CL-24D | P827877EB | Obsolete | NA | NA | Contact Customer Service |
| 782XB2CL-6 A | P827880EB | Obsolete | NA | NA | Contact Customer Service |
| 782XB2CL-6D | P827881EB | Obsolete | NA | NA | Contact Customer Service |
| 782XB2M4L-110/125D | P827059EB | Obsolete | NA | NA | Contact Customer Service |
| 782XB2M4L-120A | P827037EB | Obsolete | 792XBXM4L-120A | C927037 | Exact replacement. 792XB relays have higher rating of 12A |
| 782XB2M4L-12A | P827057EB | Obsolete | 792XBXM4L-12A | C927057 | Exact replacement. 792XB relays have higher rating of 12A |
| 782XB2M4L-12D | P827041EB | Obsolete | 792XBXM4L-12D | C927041 | Exact replacement. 792XB relays have higher rating of 12A |
| 782XB2M4L-220/240A | P827056EB | Obsolete | 792XBXM4L-240A | C927056 | Contact Customer Service |
| 782XB2M4L-24A | P827042EB | Obsolete | 792XBXM4L-24A | C927042 | Exact replacement. 792XB relays have higher rating of 12A |
| 782XB2M4L-24D | P827038EB | Obsolete | 792XBXM4L-24D | C927038 | Exact replacement. 792XB relays have higher rating of 12A |
| 782XB2M4L-48D | P827060EB | Obsolete | 792XBXM4L-48D | C927060 | Exact replacement. 792XB relays have higher rating of 12A |
| 782XB2M4L-6 A | P827058EB | Obsolete | NA | NA | Contact Customer Service |
| 782XB2M4L-6D | P827061EB | Obsolete | NA | NA | Contact Customer Service |
| 782XB3M4L-110/125D | P827067EB | Obsolete | NA | NA | Contact Customer Service |
| 782XB3M4L-120A | P827063EB | Obsolete | 792XDX3M4L-120A | C924009 | Transition to 4-pole relay with the same ratings; also transition to 4-Pole socket |
| 782XB3M4L-12A | P827065EB | Obsolete | NA | NA | Contact Customer Service |
| 782XB3M4L-12D | P827070EB | Obsolete | NA | NA | Contact Customer Service |
| 782XB3M4L-220/240A | P827062EB | Obsolete | NA | NA | Contact Customer Service |
| 782XB3M4L-24A | P827064EB | Obsolete | 792XDX3M4L-24A | C924008 | Transition to 4-pole relay with the same ratings; also transition to 4-Pole socket |
| 782XB3M4L-24D | P827069EB | Obsolete | 792XDX3M4L-24D | C924013 | Transition to 4-pole relay with the same ratings; also transition to 4-Pole socket |
| 782XB3M4L-48D | P827068EB | Obsolete | NA | NA | Contact Customer Service |
| 782XB3M4L-6 A | P827066EB | Obsolete | NA | NA | Contact Customer Service |
| 782XB3M4L-6D | P827071EB | Obsolete | NA | NA | Contact Customer Service |
| 782XBXC-220/230A | P824491EB | Obsolete | 782XBXC-240A | C827143 | Standardizing on 240 VAC Coil |
| 782XBXC-6 A | P827146EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 782XBXC-6D | P827142EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 782XBXCL-220/230A | P824492EB | Obsolete | 782XBXCL-240A | C824394 | Standardizing on 240 VAC Coil |
| 782XBXCL-6 A | P824396EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 782XBXCL-6D | P824397EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 782XBXCT-220/230A | P824507EB | Obsolete | 782XBXCT-240A | C827136 | Standardizing on 240 VAC Coil |
| 782XBXM4L-220/230A | P827003EB | Obsolete | 782XBXM4L-240A | C827004 | Standardizing on 240 VAC Coil |
| 782XBXM4L-6 A | P824509EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 782XBXM4L-6D | P827005EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 782XCX2C-110/125D | P827354EB | Obsolete | NA | NA | Contact Customer Service |
| 782XCX2C-120A | P827390EB | Obsolete | 792DXC-120A | C924127 | Transition to 4-pole relay; 792DXD rated 6 A; also transition to 4-Pole socket |
| 782XCX2C-12A | P827372EB | Obsolete | NA | NA | Contact Customer Service |
| 782XCX2C-12D | P827327EB | Obsolete | 792DXC-12D | C924129 | Transition to 4-pole relay; 792DXD rated 6 A; also transition to 4-Pole socket |
| 782XCX2C-220/240A | P827402EB | Obsolete | NA | NA | Contact Customer Service |
| 782XCX2C-24A | P827381EB | Obsolete | 792DXC-24A | C924128 | Transition to 4-pole relay; 792DXD rated 6 A; also transition to 4-Pole socket |
| 782XCX2C-24D | P827336EB | Obsolete | 792DXC-24D | C924130 | Transition to 4-pole relay; 792DXD rated 6 A; also transition to 4-Pole socket |
| 782XCX2CL-110D | P827355EB | Obsolete | NA | NA | Contact Customer Service |
| 782XCX2CL-12A | P827373EB | Obsolete | NA | NA | Contact Customer Service |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|---------------------|------------|----------|---------------------|---------|--|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 782XCX2CL-12D | P827328EB | Obsolete | NA | NA | Contact Customer Service |
| 782XCX2CL-240A | P827403EB | Obsolete | NA | NA | Contact Customer Service |
| 782XCX2CL-24A | P827382EB | Obsolete | NA | NA | Contact Customer Service |
| 782XCX2CL-24D | P827337EB | Obsolete | NA | NA | Contact Customer Service |
| 782XCX2M4L-110/125D | P827351EB | Obsolete | NA | NA | Contact Customer Service |
| 782XCX2M4L-120A | P827387EB | Obsolete | 792XDXM4L-120A | C924023 | Contact Customer Service |
| 782XCX2M4L-12A | P827369EB | Obsolete | NA | NA | Contact Customer Service |
| 782XCX2M4L-12D | P827324EB | Obsolete | 792XDXM4L-12D | C924026 | Transition to 4-pole relay with the same ratings; also transition to 4-Pole socket |
| 782XCX2M4L-220/240A | P827399EB | Obsolete | NA | NA | Contact Customer Service |
| 782XCX2M4L-24A | P827378EB | Obsolete | 792XDXM4L-24A | C924022 | Transition to 4-pole relay with the same ratings; also transition to 4-Pole socket |
| 782XCX2M4L-24D | P827333EB | Obsolete | 792XDXM4L-24D | C924027 | Transition to 4-pole relay with the same ratings; also transition to 4-Pole socket |
| 782XCX3M4L-110/125D | P827647EB | Obsolete | NA | NA | Contact Customer Service |
| 782XCX3M4L-120A | P827642EB | Obsolete | 792XDX3M4L-120A | C924009 | Transition to 4-pole relay with the same ratings; also transition to 4-Pole socket |
| 782XCX3M4L-12D | P827645EB | Obsolete | 792XDX3M4L-12D | C924012 | Transition to 4-pole relay with the same ratings; also transition to 4-Pole socket |
| 782XCX3M4L-220/240A | P827644EB | Obsolete | 792XDX3M4L-240A | C924011 | Transition to 4-pole relay with the same ratings; also transition to 4-Pole socket |
| 782XCX3M4L-24A | P827641EB | Obsolete | 792XDX3M4L-24A | C924008 | Transition to 4-pole relay with the same ratings; also transition to 4-Pole socket |
| 782XCX3M4L-24D | P827646EB | Obsolete | 792XDX3M4L-24D | C924013 | Transition to 4-pole relay with the same ratings; also transition to 4-Pole socket |
| 782XDX1C-120A | P824123EB | Obsolete | 792XDX3C-120A | C924123 | Direct replacement |
| 782XDX1C-12D | P824125EB | Obsolete | 792XDX3C-12D | C924125 | Direct replacement |
| 782XDX1C-24A | P824124EB | Obsolete | 792XDX3C-24A | C924124 | Direct replacement |
| 782XDX1C-24D | P824126EB | Obsolete | 792XDX3C-24D | C924126 | Direct replacement |
| 782XDX1CL-24A | P824116EB | Obsolete | 792XDX3CL-24A | C924116 | Direct replacement |
| 782XDX1CL-24D | P824118EB | Obsolete | 792XDX3CL-24D | C924118 | Direct replacement |
| 782XDX1CL-6 A | P824524EB | Obsolete | NA | NA | Contact Customer Service |
| 782XDX1CL-6D | P824528EB | Obsolete | NA | NA | Contact Customer Service |
| 782XDX1M4L-120A | P824009EB | Obsolete | 792XDX3M4L-120A | C924009 | Direct replacement |
| 782XDX1M4L-12D | P824012EB | Obsolete | 792XDX3M4L-12D | C924012 | Direct replacement |
| 782XDX1M4L-24D | P824013EB | Obsolete | 792XDX3M4L-24D | C924013 | Direct replacement |
| 782XDX2C-110/125D | P827563EB | Obsolete | 792XDXC-110D | C927563 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2C-120A | P824127EB | Obsolete | 792XDXC-120A | C924127 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2C-12A | P827821EB | Obsolete | 792XDXC-12A | C927821 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2C-12D | P824129EB | Obsolete | 792XDXC-12D | C924129 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2C-220/240A | P824165EB | Obsolete | 792XDXC-240A | C924165 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2C-24A | P824128EB | Obsolete | 792XDXC-24A | C924128 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2C-24D | P824130EB | Obsolete | 792XDXC-24D | C924130 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2C-48D | P824548EB | Obsolete | 792XDXC-48D | C924548 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2C-6 A | P827819EB | Obsolete | NA | NA | Contact Customer Service |
| 782XDX2C-6D | P827820EB | Obsolete | NA | NA | Contact Customer Service |
| 782XDX2CL-12D | P824121EB | Obsolete | 792XDXCL-12D | C924121 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2CL-24A | P824120EB | Obsolete | 792XDXCL-24A | C924120 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2CL-24D | P824122EB | Obsolete | 792XDXCL-24D | C924122 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|---------------------|------------|----------|---------------------|---------|--|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 782XDX2CL-6 A | P824549EB | Obsolete | NA | NA | Contact Customer Service |
| 782XDX2CL-6D | P824553EB | Obsolete | NA | NA | Contact Customer Service |
| 782XDX2M4L-110/125D | P824028EB | Obsolete | 792XDXM4L-110D | C924028 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2M4L-120A | P824023EB | Obsolete | 792XDXM4L-120A | C924023 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2M4L-12A | P827633EB | Obsolete | 792XDXM4L-12A | C927633 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2M4L-12D | P824026EB | Obsolete | 792XDXM4L-12D | C924026 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2M4L-220/240A | P824025EB | Obsolete | 792XDXM4L-240A | C924025 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2M4L-24A | P824022EB | Obsolete | 792XDXM4L-24A | C924022 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2M4L-24D | P824027EB | Obsolete | 792XDXM4L-24D | C924027 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2M4L-48D | P824217EB | Obsolete | 792XDXM4L-48D | C924217 | 782XDX2 relays rated 10 A; 792XDX relays rated 6 A |
| 782XDX2M4L-6 A | P824567EB | Obsolete | NA | NA | Contact Customer Service |
| 782XDX2M4L-6D | P824114EB | Obsolete | NA | NA | Contact Customer Service |
| 782XDX3CL-12D | P824578EB | Obsolete | 792XDX3CL-12D | C924117 | Direct replacement |
| 782XDX3CL-24A | P824573EB | Obsolete | 792XDX3CL-24A | C924116 | Direct replacement |
| 782XDX3CL-24D | P824579EB | Obsolete | 792XDX3CL-24D | C924118 | Direct replacement |
| 782XDX3CL-6 A | P824571EB | Obsolete | NA | NA | Contact Customer Service |
| 782XDX3CL-6D | P824577EB | Obsolete | NA | NA | Contact Customer Service |
| 782XDX3M4L-110/125D | P824007EB | Obsolete | NA | NA | Contact Customer Service |
| 782XDX3M4L-120A | P824002EB | Obsolete | 792XDX3M4L-120A | C924009 | Direct replacement |
| 782XDX3M4L-12A | P824594EB | Obsolete | NA | NA | Contact Customer Service |
| 782XDX3M4L-12D | P824005EB | Obsolete | 792XDX3M4L-12D | C924012 | Direct replacement |
| 782XDX3M4L-220/240A | P824004EB | Obsolete | NA | NA | Contact Customer Service |
| 782XDX3M4L-24A | P824001EB | Obsolete | 792XDX3M4L-24A | C924008 | Direct replacement |
| 782XDX3M4L-24D | P824006EB | Obsolete | 792XDX3M4L-24D | C924013 | Direct replacement |
| 782XDX3M4L-48D | P824219EB | Obsolete | 792XDX3M4L-48D | C924215 | Direct replacement |
| 783XCXC-220/230A | P833206EB | Obsolete | 783XCXC-240A | C833029 | Standardizing on 240 VAC Coil |
| 783XCXC-36D | P833192EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 783XCXC-6 A | P833066EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 783XCXC-6D | P833090EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 783XCXCL-220/230A | P833208EB | Obsolete | 783XCXCL-240A | C833042 | Standardizing on 240 VAC Coil |
| 783XCXCL-6 A | P833067EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 783XCXCL-6D | P833067EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 783XCXM4L-220/230A | P833128EB | Obsolete | 783XCXM4L-240A | C833006 | Standardizing on 240 VAC Coil |
| 783XCXM4L-6 A | P833127EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 783XCXM4L-6D | P833015EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 784XDXC-220/230A | P844231EB | Obsolete | 784XDXC-240A | C844038 | Standardizing on 240 VAC Coil |
| 784XDXC-6 A | P844068EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 784XDXC-6D | P844092EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 784XDXC-220/230A | P844229EB | Obsolete | 784XDXC-240A | C844042 | Standardizing on 240 VAC Coil |
| 784XDXM4L-220/230A | P844009EB | Obsolete | 784XDXM4L-240A | C844008 | Standardizing on 240 VAC Coil |
| 784XDXM4L-6 A | P844011EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 784XDXM4L-6D | P844007EB | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 785XBXC-120A | I858020E | Obsolete | NA | NA | Contact Customer Service |
| 785XBXC-12D | I858004E | Obsolete | NA | NA | Contact Customer Service |
| 785XBXC-240A | I858019E | Obsolete | NA | NA | Contact Customer Service |
| 785XBXC-24A | I858021E | Obsolete | NA | NA | Contact Customer Service |
| 785XBXC-24D | I858019E | Obsolete | NA | NA | Contact Customer Service |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|-------------------|------------|----------|--------------------------|--------------------|---|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 785XBXCD-12D | I858037E | Obsolete | NA | NA | Contact Customer Service |
| 785XBXCD-24D | I858036E | Obsolete | NA | NA | Contact Customer Service |
| 788XAXC-120A | P887390E | Obsolete | 788XBXRC-120A | C887400 | Replacement product is rated 10 A & has 2 poles |
| 788XAXC-12D | P887393E | Obsolete | 788XBXRC-12D | C887403 | Replacement product is rated 10 A & has 2 poles |
| 788XAXC-220/240A | P887391E | Obsolete | 788XBXRC-240A | C887401 | Replacement product is rated 10 A & has 2 poles |
| 788XAXC-24A | P887389E | Obsolete | 788XBXRC-24A | C887399 | Replacement product is rated 10 A & has 2 poles |
| 788XAXC-24D | P887394E | Obsolete | 788XBXRC-24D | C887404 | Replacement product is rated 10 A & has 2 poles |
| 788XAXC1-120A | P887478E | Obsolete | 788XBXRC1-120A | C887488 | Replacement product is rated 10 A & has 2 poles |
| 788XAXC1-12D | P887481E | Obsolete | 788XBXRC1-12D | C887491 | Replacement product is rated 10 A & has 2 poles |
| 788XAXC1-220/240A | P887479E | Obsolete | 788XBXRC1-240A | C887489 | Replacement product is rated 10 A & has a 240 VAC coil |
| 788XAXC1-24A | P887477E | Obsolete | 788XBXRC1-24A | C887487 | Replacement product is rated 10 A & has 2 poles |
| 788XAXC1-24D | P887482E | Obsolete | 788XBXRC1-24D | C887492 | Replacement product is rated 10 A & has 2 poles |
| 788XAXC3-120A | P887879E | Obsolete | 781XAXRC-120A + 16-781C1 | C811082 + P981635E | Different form & fit. Replacement product is rated 15 A, & uses accessory for top flange panel mounting |
| 788XAXC3-12D | P887880E | Obsolete | 781XAXRC-12D + 16-781C1 | C811088 + P981635E | Different form & fit. Replacement product is rated 15 A, & uses accessory for top flange panel mounting |
| 788XAXC3-220/240A | P887881E | Obsolete | 781XAXRC-240A + 16-781C1 | C811081 + P981635E | Different form & fit. Replacement product is rated 15 A, & uses accessory for top flange panel mounting |
| 788XAXC3-24A | P887882E | Obsolete | 781XAXRC-24A + 16-781C1 | C811083 + P981635E | Different form & fit. Replacement product is rated 15 A, & uses accessory for top flange panel mounting |
| 788XAXC3-24D | P887883E | Obsolete | 781XAXRC-24D + 16-781C1 | C811087 + P981635E | Different form & fit. Replacement product is rated 15 A, & uses accessory for top flange panel mounting |
| 788XAXCL-12D | P887885E | Obsolete | 788XBXRCL-12D | C887575 | Different form. Replacement product is rated 10 A & has 2 poles |
| 788XAXCL-240A | P887886E | Obsolete | 788XBXRCL-240A | C887571 | Different form. Replacement product is rated 10 A & has 2 poles |
| 788XAXCL-24A | P887887E | Obsolete | 788XBXRCL-24A | C887574 | Different form. Replacement product is rated 10 A & has 2 poles |
| 788XAXCL-24D | P887888E | Obsolete | 788XBXRCL-24D | C887572 | Different form. Replacement product is rated 10 A & has 2 poles |
| 788AXM4L-120A | P887889E | Obsolete | 788XBXR4L-120A | C887002 | Different form. Replacement product is rated 10 A & has 2 poles |
| 788AXM4L-12D | P887890E | Obsolete | 788XBXR4L-12D | C887005 | Different form. Replacement product is rated 10 A & has 2 poles |
| 788AXM4L-24A | P887892E | Obsolete | 788XBXR4L-24A | C887001 | Different form. Replacement product is rated 10 A & has 2 poles |
| 788AXM4L-24D | P887893E | Obsolete | 788XBXR4L-24D | C887006 | Different form. Replacement product is rated 10 A & has 2 poles |
| 788XB69C-110D | P887433E | Obsolete | 788XB69C-110D | C887433 | Replacement product has identical motor load ratings of 3 A at 150 VDC & a resistive current rating of 10 A |
| 788XB69C-120A | P887428E | Obsolete | 788XB69C-120A | C887428 | Replacement product has identical motor load ratings of 3 A at 150 VDC & a resistive current rating of 10 A |
| 788XB69C-12A | P887426E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 788XB69C-12D | P887431E | Obsolete | 788XB69C-12D | C887431 | Replacement product has identical motor load ratings of 3 A at 150 VDC & a resistive current rating of 10 A |
| 788XB69C-24D | P887432E | Obsolete | 788XB69C-24D | C887432 | Replacement product has identical motor load ratings of 3 A at 150 VDC & a resistive current rating of 10 A |
| 788BXC-110/125D | P887405E | Obsolete | 788BXC-110D | C887405 | Replacement product is rated 10 A |
| 788BXC-120A | P887400E | Obsolete | 788BXC-120A | C887400 | Replacement product is rated 10 A |
| 788BXC-12A | P887398E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 788BXC-12D | P887403E | Obsolete | 788BXC-12D | C887403 | Replacement product is rated 10 A |
| 788BXC-220/240A | P887401E | Obsolete | 788BXC-240A | C887401 | Replacement product is rated 10 A |
| 788BXC-24A | P887399E | Obsolete | 788BXC-24A | C887399 | Replacement product is rated 10 A |
| 788BXC-24D | P887404E | Obsolete | 788BXC-24D | C887404 | Replacement product is rated 10 A |
| 788BXC-48D | P887583E | Obsolete | 788BXC-48D | C887583 | Replacement product is rated 10 A |
| 788BXC1-110/125D | P887493E | Obsolete | 788BXC1-110D | C887895 | Replacement product is rated 10 A |
| 788BXC1-120A | P887488E | Obsolete | 788BXC1-120A | C887488 | Replacement product is rated 10 A |
| 788BXC1-12A | P887486E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|--------------------|------------|----------|---------------------|---------|--|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 788XBXC1-12D | P887491E | Obsolete | 788XBXRC1-12D | C887491 | Replacement product is rated 10 A |
| 788XBXC1-220/240A | P887489E | Obsolete | 788XBXRC1-240A | C887489 | Replacement product is rated 10 A |
| 788XBXC1-24A | P887487E | Obsolete | 788XBXRC1-24A | C887487 | Replacement product is rated 10 A |
| 788XBXC1-24D | P887492E | Obsolete | 788XBXRC1-24D | C887492 | Replacement product is rated 10 A |
| 788XBXCL-110D | P887573E | Obsolete | 788XBXRCL-110D | C887136 | Replacement product is rated 10 A |
| 788XBXCL-12A | P887585E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 788XBXCL-12D | P887575E | Obsolete | 788XBXRCL-12D | C887575 | Replacement product is rated 10 A |
| 788XBXCL-240A | P887571E | Obsolete | 788XBXRCL-240A | C887571 | Replacement product is rated 10 A |
| 788XBXCL-24A | P887574E | Obsolete | 788XBXRCL-24A | C887574 | Replacement product is rated 10 A |
| 788XBXCL-24D | P887572E | Obsolete | 788XBXRCL-24D | C887572 | Replacement product is rated 10 A |
| 788XBXM4L-110/125D | P887007E | Obsolete | NA | NA | Contact Customer Service |
| 788XBXM4L-120A | P887002E | Obsolete | 788XBXR4M4L-120A | C887002 | Replacement product is rated 10 A |
| 788XBXM4L-12A | P887019E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 788XBXM4L-12D | P887005E | Obsolete | 788XBXR4M4L-12D | C887005 | Replacement product is rated 10 A |
| 788XBXM4L-220/240A | P887004E | Obsolete | NA | NA | Contact Customer Service |
| 788XBXM4L-24A | P887001E | Obsolete | 788XBXR4M4L-24A | C887001 | Replacement product is rated 10 A |
| 788XBXM4L-24D | P887006E | Obsolete | 788XBXR4M4L-24D | C887006 | Replacement product is rated 10 A |
| 788XBXM4L-48D | P887017E | Obsolete | 788XBXR4M4L-48D | C887017 | Replacement product is rated 10 A |
| 788XBXM4L-6 A | P887018E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 788XBXM4L-6D | P887016E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 788XCXC-110/125D | P887415E | Obsolete | 788XCXRC-110D | C887415 | Replacement product is rated 10 A |
| 788XCXC-120A | P887410E | Obsolete | 788XCXRC-120A | C887410 | Replacement product is rated 10 A |
| 788XCXC-12A | P887408E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 788XCXC-12D | P887413E | Obsolete | 788XCXRC-12D | C887413 | Replacement product is rated 10 A |
| 788XCXC-220/240A | P887411E | Obsolete | 788XCXRC-240A | C887411 | Replacement product is rated 10 A |
| 788XCXC-24A | P887409E | Obsolete | 788XCXRC-24A | C887409 | Replacement product is rated 10 A |
| 788XCXC-24D | P887414E | Obsolete | 788XCXRC-24D | C887414 | Replacement product is rated 10 A |
| 788XCXC-48D | P887589E | Obsolete | 788XCXRC-48D | C887589 | Replacement product is rated 10 A |
| 788XCXC1-110/125D | P887503E | Obsolete | 788XCXRC1-110D | C887503 | Replacement product is rated 10 A |
| 788XCXC1-120A | P887498E | Obsolete | 788XCXRC1-120A | C887498 | Replacement product is rated 10 A |
| 788XCXC1-12A | P887496E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 788XCXC1-12D | P887501E | Obsolete | 788XCXRC1-12D | C887501 | Replacement product is rated 10 A |
| 788XCXC1-220/240A | P887499E | Obsolete | 788XCXRC1-240A | C887499 | Replacement product is rated 10 A |
| 788XCXC1-24A | P887497E | Obsolete | 788XCXRC1-24A | C887497 | Replacement product is rated 10 A |
| 788XCXC1-24D | P887502E | Obsolete | 788XCXRC1-24D | C887502 | Replacement product is rated 10 A |
| 788XCXC1-48D | P887902E | Obsolete | 788XCXRC1-48D | C887902 | Replacement product is rated 10 A |
| 788XCXCL-110D | P887579E | Obsolete | 788XCXRCL-110D | C887175 | Replacement product is rated 10 A |
| 788XCXCL-12A | P887591E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 788XCXCL-12D | P887580E | Obsolete | 788XCXRCL-12D | C887580 | Replacement product is rated 10 A |
| 788XCXCL-240A | P887577E | Obsolete | 788XCXRCL-240A | C887577 | Replacement product is rated 10 A |
| 788XCXCL-24A | P887581E | Obsolete | 788XCXRCL-24A | C887581 | Replacement product is rated 10 A |
| 788XCXCL-24D | P887578E | Obsolete | 788XCXRCL-24D | C887578 | Replacement product is rated 10 A |
| 788XCXM4L-110/125D | P883007E | Obsolete | 788XCXR4M4L-110D | C883007 | Replacement product is rated 10 A |
| 788XCXM4L-120A | P883002E | Obsolete | 788XCXR4M4L-120A | C883002 | Replacement product is rated 10 A |
| 788XCXM4L-12A | P883020E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 788XCXM4L-12D | P883005E | Obsolete | 788XCXR4M4L-12D | C883005 | Replacement product is rated 10 A |
| 788XCXM4L-220/240A | P883004E | Obsolete | 788XCXR4M4L-240A | C883004 | Replacement product is rated 10 A |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|-------------------|------------|----------|--|----------------------|--|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| 788XCXM4L-24A | P883015E | Obsolete | 788XCXRM4L-24A | C883015 | Replacement product is rated 10 A |
| 788XCXM4L-24D | P883006E | Obsolete | 788XCXRM4L-24D | C883006 | Replacement product is rated 10 A |
| 788XCXM4L-48D | P883018E | Obsolete | 788XCXRM4L-48D | C883018 | Replacement product is rated 10 A |
| 788XCXM4L-6 A | P887142E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 788XCXM4L-6D | P883017E | Obsolete | NA | NA | Contact Customer Service to transition to different coil voltage |
| 78ACXSX-5 | P784002 | Obsolete | 782XD1C-120A | P824123EB | Direct replacement |
| 78ARCSX-3 | P787094 | Obsolete | 782XBXC-24A + 16-782C1 Flange Adapter | P827145EB + P981637E | Not a direct replacement - contact Customer Service |
| 78ARCSX-5 | P787089 | Obsolete | 782XBXC-120A + 16-782C1 Flange Adapter | P827144EB + P981637E | Not a direct replacement - contact Customer Service |
| 78ARCSX-9 | P787001 | Obsolete | 782XBXC-24A | P827145EB | Direct replacement |
| 78ARPCX-24 | E781007 | Obsolete | 782XAXCT-120A | P821015EB | Direct replacement |
| 78ARPCX-5 | E787003 | Obsolete | 782XBXCCT-120A | P827137EB | Direct replacement |
| 78ATEPCX-3 | P784191 | Obsolete | 782XD3CT-24A | P827640EB | Not a direct replacement - contact Customer Service |
| 78CSX-3 | P784005 | Obsolete | 782XD1C-24D | P824155EB | Direct replacement |
| 78ERCSX-4 | P787101 | Obsolete | 782XBXC-24D | P827143EB | Not a direct replacement - contact Customer Service |
| 78KCSX-13 | P784045 | Obsolete | 782XD2C-24D | P824130EB | Direct replacement |
| 78KEPCX-13 | P784192 | Obsolete | 782XDCT-24D | P824039E | Not a direct replacement - contact Customer Service |
| 78RCSX-8 | P787004 | Obsolete | 782XBXC-24D | P827140EB | Direct replacement |
| 78RPCX-2 | P787012 | Obsolete | 782XBXCCT-12D | P827134EB | Direct replacement |
| 78RPCX-3 | P781018 | Obsolete | 782XBXCCT-24D | P827136EB | Direct replacement |
| 7PCX-1/MMS105 | I071001E | Obsolete | 276AXH-5D | I761008E | Not a direct replacement: Check product size & pin spacings |
| 7PCX-10/MMS204 | I077009E | Obsolete | NA | NA | Contact Customer Service |
| 7PCX-3/MMS112 | I071003E | Obsolete | 276AXH-12D | I761011E | Not a direct replacement: Check product size & pin spacings |
| 7PCX-4/MMS124 | I071004E | Obsolete | 276AXH-24D | I761012E | Not a direct replacement: Check product size & pin spacings |
| 7PCX-5/MMS205 | I077001E | Obsolete | 276AXH-5D | I761008E | Not a direct replacement: Check product size pin spacings & contact configuration. |
| 7PCX-7/MMS212 | I077003E | Obsolete | 976XBXH-12D | P967006E | Not a direct replacement: Check product size & pin spacings |
| 7PCX-8/MMS224 | I077004E | Obsolete | 976XBXH-24D | P967007E | Not a direct replacement: Check product size & pin spacings |
| 976XAX97H-240A | P961003E | Obsolete | NA | NA | Contact Customer Service |
| 976XAX97H-48D | P961018E | Obsolete | NA | NA | Contact Customer Service |
| 976XAX97H-5D | P961015E | Obsolete | NA | NA | Contact Customer Service |
| 976XAX97H-6DC | P961016 | Obsolete | NA | NA | Contact Customer Service |
| 976XAXH-48D | P961013E | Obsolete | NA | NA | Contact Customer Service |
| 976XAXH-5D | P961010E | Obsolete | NA | NA | Contact Customer Service |
| 976XAXH-6D | P961011E | Obsolete | NA | NA | Contact Customer Service |
| 976XBXH-5D | P967004E | Obsolete | NA | NA | Contact Customer Service |
| 976XBXH-6D | P967005E | Obsolete | NA | NA | Contact Customer Service |
| F300XB69C1-12D | I037005 | Obsolete | NA | NA | Contact Customer Service |
| F300XB69C3-12D | I007109 | Obsolete | NA | NA | Contact Customer Service |
| F300XBXC-110/125D | I007143 | Obsolete | NA | NA | Coil voltage no longer available |
| F300XBXC1-120A | I007118 | Obsolete | 300XBXC1-120A | C007010 | No difference |
| F300XBXC1-12D | I007002 | Obsolete | 300XBXC1-12D | C007002 | No difference |
| F300XBXC1-24D | I007003 | Obsolete | 300XBXC1-24D | C007003 | No difference |
| F300XBXC2-125D | I007092 | Obsolete | NA | NA | Coil voltage & anti-rotation tab no longer available |
| F300XBXC3-24A | I007122 | Obsolete | 300XBXC1-24A | C007008 | Move to from top flange to side flange |
| F300XBXC4-120A | I007145 | Obsolete | 300XBXC1-120A | C007010 | Move to from top DIN mount to side flange |
| F300XBXCCT-125D | I007173 | Obsolete | NA | NA | Coil voltage & PCB terminals no longer available |

Master Obsolescence List

For Magnecraft relays, sockets & accessories

Customer Service 1-847-441-2540
List is sorted numerically by Catalog Number

| CATALOG NUMBER | SKU NUMBER | STATUS | ALTERNATIVE PRODUCT | | |
|----------------|------------|----------|---------------------|----------|---|
| | | | CATALOG NO. | SKU NO. | DIFFERENCES |
| KHS-17A11-120 | NA | Obsolete | 782DXH10-120A | P824033E | Current version |
| KHS-17A11-240 | NA | Obsolete | 782DXH10-240A | P824034E | Current version |
| KHS-17A12-120 | NA | Obsolete | 782DXH21-120A | P824044E | Current version |
| KHS-17D11-110 | NA | Obsolete | 782DXH10-110D | P824039E | Current version |
| KHS-17D11-120 | NA | Obsolete | 782DXH10-12D | P824036E | Current version |
| KHS-17D11-24 | NA | Obsolete | 782DXH10-24D | P824037E | Current version |
| KHS-17D12-12 | NA | Obsolete | 782DXH21-12D | P824047E | Current version |
| KHS-17D12-24 | NA | Obsolete | 782DXH21-24D | P824048E | Current version |
| TDRSOXB-120V | PTDR7012E | Obsolete | 822TD10H-UNI | PE82103E | Replacement product is multi-functional integrated DIN rail mount timer that replaces both the TDRSOX plug-in timer & mating socket. Check pin configuration. |
| TDRSOXB-12V | PTDR7014E | Obsolete | 822TD10H-UNI | PE82103E | Replacement product is multi-functional integrated DIN rail mount timer that replaces both the TDRSOX plug-in timer & mating socket. Check pin configuration. |
| TDRSOXB-24V | PTDR7013E | Obsolete | 822TD10H-UNI | PE82103E | Replacement product is multi-functional integrated DIN rail mount timer that replaces both the TDRSOX plug-in timer & mating socket. Check pin configuration. |
| TDRSOXP-120V | PTDR7020E | Obsolete | 822TD10H-UNI | PE82103E | Replacement product is multi-functional integrated DIN rail mount timer that replaces both the TDRSOX plug-in timer & mating socket. Check pin configuration. |
| TDRSOXP-12V | PTDR7022E | Obsolete | 822TD10H-UNI | PE82103E | Replacement product is multi-functional integrated DIN rail mount timer that replaces both the TDRSOX plug-in timer & mating socket. Check pin configuration. |
| TDRSOXP-240A | PTDR7019E | Obsolete | 822TD10H-UNI | PE82103E | Replacement product is multi-functional integrated DIN rail mount timer that replaces both the TDRSOX plug-in timer & mating socket. Check pin configuration. |
| TDRSOXP-24V | PTDR7021E | Obsolete | 822TD10H-UNI | PE82103E | Replacement product is multi-functional integrated DIN rail mount timer that replaces both the TDRSOX plug-in timer & mating socket. Check pin configuration. |
| TDRSRXB-120V | PTDR7008E | Obsolete | 822TD10H-UNI | PE82103E | Replacement product is multi-functional integrated DIN rail mount timer that replaces both the TDRSRX plug-in timer & mating socket. Check pin configuration. |
| TDRSRXB-12V | PTDR7010E | Obsolete | 822TD10H-UNI | PE82103E | Replacement product is multi-functional integrated DIN rail mount timer that replaces both the TDRSRX plug-in timer & mating socket. Check pin configuration. |
| TDRSRXB-24V | PTDR7009E | Obsolete | 822TD10H-UNI | PE82103E | Replacement product is multi-functional integrated DIN rail mount timer that replaces both the TDRSRX plug-in timer & mating socket. Check pin configuration. |
| TDRSRXP-120V | PTDR7016E | Obsolete | 822TD10H-UNI | PE82103E | Replacement product is multi-functional integrated DIN rail mount timer that replaces both the TDRSRX plug-in timer & mating socket. Check pin configuration. |
| TDRSRXP-12V | PTDR7018E | Obsolete | 822TD10H-UNI | PE82103E | Replacement product is multi-functional integrated DIN rail mount timer that replaces both the TDRSRX plug-in timer & mating socket. Check pin configuration. |
| TDRSRXP-24V | PTDR7017E | Obsolete | 822TD10H-UNI | PE82103E | Replacement product is multi-functional integrated DIN rail mount timer that replaces both the TDRSRX plug-in timer & mating socket. Check pin configuration. |

Schneider Electric USA, Inc.

1300 S . Wolf Rd.
Des Plaines, IL 60018
Tel: 847-441-2540

www.serelays.com

The information in this document is provided for the convenience of our customers . While this information is believed to be accurate, Schneider Electric reserves the right to make updates and changes without prior notification and assumes no liability for any errors or omissions.

Design: Schneider Electric

© 2014 Schneider Electric. All Rights Reserved. Schneider Electric and Magnecraft are trademarks owned by Schneider Electric Industries SAS or its affiliated companies. All other trademarks are the property of their respective owners.

Last Modified: 11/11/14